

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004205/UTY3Q2**Date:** 30/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00232742101

Claimant Vehicle No : SGV4854C **Insured Vehicle No :** SJQ7437U

Date of Loss: 28/04/2022 Nature of Claim: TP Claim No: SNM22D202920/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV4854C**

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2915400

Reg. Date: 17/06/2007 (Man. Year: 2007) Chassis No: ZNE100367553

Colour: Maroon Odometer: 108312 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,663.85	2,914.77	5,749.08	66.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	2,120.00	1,780.00	45.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,563.85	5,034.77	7,529.08	59.93
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	12,563.85	4,000.00	8,563.85	68.16
+ GST 7.00/7.00% (S\$)	879.47	280.00	599.47	68.16
Nett Amount (S\$)	13,443.32	4,280.00	9,163.32	68.16

INSPECTION

Date of Assignment: 06/05/2022

Date Inspected: 10/05/2022 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV4854C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S HEADLAMP	Holder Cracked	1,450.00 FL	*858.10 FL
2	1		*O/S HEADLAMP LOWER BRACKET	Not Necessary	85.00 FL	*- FL
3	1		*O/S HEADLAMP TOP PANEL	Repair	250.00 FL	*- FL
4	1		*O/S FRONT FENDER	Repair	955.90 FL	*- FL
5	1		*O/S FRONT FENDER INNER COWLING	Not Necessary	167.10 FL	*- FL
6	8		*O/S FRONT FENDER INNER COWLING CLIPS	Not Necessary	40.00 FL	*- FL
7	1		*BONNET CHROME MOULDING	Not Necessary	226.10 FL	*- FL
8	1		*FRONT BUMPER	Distorted	750.00 FL	*665.10 FL
9	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
10	1		*FRONT BUMPER SPONGE	Torn	58.30 FL	*58.30 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	272.70 FL	*272.70 FL
12	1		*FRONT BUMPER LOWER SPOILER	Repair	348.70 FL	*- FL
13	1		*FRONT BUMPER SIDE RETAIER O/S	Bent	60.30 FL	*60.30 FL
14	1		*FRONT BUMPER FOG LAMP COVER O/S	Not Necessary	72.20 FL	*- FL
15	7		*FRONT BUMPER TOP COVER CLIPS	Not Necessary	35.00 FL	*- FL
16	1		*WASHER TANK	Not Necessary	95.00 FL	*- FL
17	1		*TAILGATE LID	Repair	415.50 FL	*- FL
18	1		*TAILGATE LID LOCK TOP	Not Necessary	395.80 FL	*- FL
19	1		*TAILGATE LID CATCH BOTTOM	Not Necessary	39.20 FL	*- FL
20	1		*TAILGATE LID INNER TRIM BOARD	Not Necessary	480.00 FL	*- FL
21	1		*TAILGATE LID EMBLEM	Not Necessary	75.80 FL	*- FL
22	1		*TAILGATE LID WEATHERSTRIP	Not Necessary	320.00 FL	*- FL
23	2		*TAILLAMP	Not Necessary	602.80 FL	*- FL
24	2		*TAILLAMP CLIPS	Not Necessary	10.20 FL	*- FL
25	1		*REAR BUMPER	Distorted	680.00 FL	*545.00 FL
26	2		*REAR BUMPER SIDE RETAINER	Necessary	120.00 FL	*120.00 FL
27	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
28	1		*REAR BUMPER REFLECTOR	O/S Broken	110.20 FL	*55.10 FL
29	1		*REAR END PANEL	Dented / Bent	485.10 FL	*485.10 FL
30	1		*REAR END PANEL INNER GARNISH	Not Necessary	285.10 FL	*- FL
31	1		*REAR EXHAUST BOX	Repair	1,250.00 FL	*- FL
32	1		*REAR WINDSCREEN RUBBER	Not Necessary	235.80 FL	*- FL
33	1		*REAR CAMERA	Cracked	350.00 FS	*300.00 FS
34	1		*SET REAR BUMPER PARKING SENSOR	Shorted	250.00 FS	*200.00 FS
35	1		*REAR WINDSCREEN PRIMER	Not Necessary	50.00 FS	*- FS
36	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
37	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
38	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,281.80	3,719.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,617.95	804.93
Total Parts (\$\$)	8,663.85	2,914.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING ON THE AFFECTED AREAS	New	200.00	40.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED FRONT & REAR	New	100.00	30.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	80.00	0.00
6	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	80.00	0.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTEN FRONT AND REAR THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	1,000.00
8	PUTTY AND SPRAY PAINTING FRONT & REAR OF THE AFFECTED PORTION	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			3,900.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >