

Supplementary item

OER

bcc LER

Ignite Motors Pte Ltd

1 Sin Ming Industrial Estate Sector C #01-117 Singapore 575636
Tel: 83831280

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : GBJ 3098Y
Made : Toyota
Model : Hiace
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 498.10	\$ 498.10
2	Front Bumper Tow Hook Cover	1	\$ 48.00	\$ 48.00
3	Front Bumper Fog Lamp Cover RH	1	\$ 76.00	\$ 76.00
4	Front Bumper Fog Lamp Cover LH	1	\$ 76.00	\$ 76.00
5	Front Bumper Fog Lamp RH	1	\$ 357.20	\$ 357.20
6	Front Bumper Fog Lamp LH	1	\$ 357.20	\$ 357.20
7	Front Bumper Side Retainer RH	1	\$ 141.10	\$ 141.10
8	Front Bumper Side Retainer LH	1	\$ 141.10	\$ 141.10
9	Front Bumper Centre Beam	1	\$ 425.00	\$ 425.00
10	Front Bumper Reinforcement	1	\$ 450.00	\$ 450.00
11	Front Grille Upper Base	1	\$ 471.10	\$ 471.10
12	Front Grille Lower	1	\$ 198.60	\$ 198.60
13	Front Grille Cover Garnish Upper	1	\$ 214.70	\$ 214.70
14	Front Grille Cover Garnish Lower	1	\$ 329.20	\$ 329.20
15	Front Headlamp Assembly RH	1	\$ 2,945.00	\$ 2,945.00
16	Front Headlamp Assembly LH	1	\$ 2,945.00	\$ 2,945.00
17	Wiper Panel Garnish	1	\$ 593.10	\$ 593.10
18	Front Bonnet	1	\$ 1,135.00	\$ 1,135.00
19	Front Bonnet Lock	1	\$ 140.00	\$ 140.00
20	Front Bonnet Emblem	1	\$ 75.00	\$ 75.00
21	Front Corner Panel RH	1	\$ 295.50	\$ 295.50
22	Front Corner Panel LH	1	\$ 295.50	\$ 295.50
23	Front Support Panel	1	\$ 695.00	\$ 695.00
24	Front Brace Panel	1	\$ 89.50	\$ 89.50
25	Aircon Condenser	1	\$ 1,480.00	\$ 1,480.00
26	Aircon Condenser Bracket	4	\$ 128.00	\$ 512.00
27	Radiator	1	\$ 2,250.00	\$ 2,250.00
28	Radiator Spare Tank	1	\$ 108.40	\$ 108.40
29	Air Cooler	1	\$ 1,450.00	\$ 1,450.00
30	Air Cooler Air Guard	2	\$ 211.10	\$ 422.20
31	Air Cooler Bracket	2	\$ 298.10	\$ 596.20
32	Cooler Air Guard Rubber	2	\$ 110.00	\$ 220.00

BRV
NSX
DLV
NDX
DLV
NDX
NECV
BTV
BTV
BRV
BRV
NSX
BRV
BRV
NSX
DDV
JMV
NECV
NDX
BTV
BTV
BTV
DDV
NDX
DDV
NDX

33	Air Cleaner Box	1	\$	799.80	\$	799.80	BRV
34	Air Cleaner Box Inlet	1	\$	298.70	\$	298.70	NSX
35	Wiring Harness Cover Box RH	1	\$	212.50	\$	212.50	
36	Brake Master Pump	1	\$	784.00	\$	784.00	
37	Brake Master Pump Booster	1	\$	1,219.80	\$	1,219.80	
38	Brake Booster Switch	1	\$	181.90	\$	181.90	
39	Brake Booster Pipe	1	\$	298.00	\$	298.00	NDI
40	Brake Pipe	2	\$	345.00	\$	690.00	
41	Brake Fuel Container	1	\$	268.00	\$	268.00	
42	Clutch Pump Upper	1	\$	350.00	\$	350.00	
43	Clutch Pump Pipe	1	\$	145.10	\$	145.10	
44	Front Aircon Cooling Coil	1	\$	1,800.00	\$	1,800.00	NDI
45	Front Aircon Blower	1	\$	1,371.10	\$	1,371.10	
46	Front Dashboard Panel	1	\$	1,245.00	\$	1,245.00	NDX
47	Front Dashboard Assembly	1	\$	1,320.20	\$	1,320.20	
48	Front Windscreen Moulding	1	\$	95.20	\$	95.20	NDX
49	Front Driver's Seat Belt	1	\$	1,250.00	\$	1,250.00	
50	Rear Tailgate	1	\$	2,051.60	\$	2,051.60	DDV
51	Rear Tailgate Outer Garnish	1	\$	236.50	\$	236.50	BRV
52	Rear Tailgate Emblem	1	\$	75.80	\$	75.80	NEC
53	Rear Tailgate Number Plate Lamp	2	\$	62.25	\$	124.50	BRV
54	Rear Tailgate Corner Garnish RH	1	\$	86.20	\$	86.20	
55	Rear Tailgate Corner Garnish LH	1	\$	86.20	\$	86.20	NSX
56	Rear Tailgate Stopper	2	\$	24.60	\$	49.20	NNX
57	Rear Tailgate Damper	2	\$	58.00	\$	116.00	BTU
58	Rear Tailgate Inner Trim	1	\$	272.60	\$	272.60	BRV
59	Rear Tailgate Inner Lock	1	\$	268.70	\$	268.70	JMV
60	Rear Tailgate Lower Lock	1	\$	38.90	\$	38.90	BTU
61	Rear Tailgate Outer Lock Handle	1	\$	175.80	\$	175.80	BRV
62	Rear Tailgate Lock Motor	1	\$	545.00	\$	545.00	NSX
63	Rear Tailgate Weatherstrip	1	\$	329.10	\$	329.10	TNV
64	Rear Tailgate Weatherstrip Protector	1	\$	125.70	\$	125.70	DISV
65	Rear Taillamp Assembly RH	1	\$	354.80	\$	354.80	BRV
66	Rear Taillamp Assembly LH	1	\$	354.80	\$	354.80	BRV
67	Rear Taillamp Panel RH	1	\$	350.00	\$	350.00	NDX
68	Rear Taillamp Panel LH	1	\$	350.00	\$	350.00	DDV
69	Rear Taillamp Lower Garnish RH	1	\$	98.30	\$	98.30	
70	Rear Taillamp Lower Garnish LH	1	\$	98.30	\$	98.30	NSX
71	Rear Taillamp Lower Garnish Retainer RH	1	\$	48.90	\$	48.90	
72	Rear Taillamp Lower Garnish Retainer LH	1	\$	48.90	\$	48.90	NEC
73	Rear Bumper	1	\$	410.60	\$	410.60	BRV
74	Rear Bumper Lower Bracket	4	\$	29.00	\$	116.00	BTU
75	Rear Bumper Side Retainer RH	1	\$	65.20	\$	65.20	
76	Rear Bumper Side Retainer LH	1	\$	65.20	\$	65.20	NEC
77	Rear End Panel (Inner)	1	\$	822.30	\$	822.30	DDV

78	Rear End Panel (Outer)	1	\$	597.00	\$	597.00	DRV	
79	Rear End Panel Side RH	1	\$	362.10	\$	362.10	} DDV	
80	Rear End Panel Side LH	1	\$	362.10	\$	362.10		
81	Rear Floor Panel Mat	1	\$	796.00	\$	796.00	TNV	
82	Rear Floor Panel	1	\$	1,960.00	\$	1,960.00	DDV	
83	Rear Exhaust Pipe	1	\$	442.00	\$	442.00	} NDI	
84	Rear Exhaust Pipe Gasket	1	\$	18.00	\$	18.00		
85	Rear Exhaust Pipe Mounting	1	\$	25.00	\$	25.00		
86	Rear Spare Tyre Carriage	1	\$	237.97	\$	237.97	DISV	
87	Rear Spare Tyre Carriage Bracket	1	\$	243.10	\$	243.10	BTV	
88	Rear Spare Tyre Carriage Screw	1	\$	68.30	\$	68.30	MIS	
89	Rear Side Panel Outer RH	1	\$	1,848.00	\$	1,848.00	NDX	
90	Rear Side Panel Outer LH	1	\$	1,848.00	\$	1,848.00	DDV	
91	Rear Side Panel Inner RH	1	\$	1,270.20	\$	1,270.20	NDX	
92	Rear Side Panel Inner LH	1	\$	1,270.20	\$	1,270.20	DLV	
93	Rear Side Lower Corner Inner Panel RH	1	\$	187.50	\$	187.50	NDX	
94	Rear Side Lower Corner Inner Panel LH	1	\$	187.50	\$	187.50	DDV	
95	Rear Side Panel Inner Trim Board RH	1	\$	198.40	\$	198.40	NDX	
96	Rear Side Panel Inner Trim Board LH	1	\$	198.40	\$	198.40	BRV	
97	Rear Side Inner Lower Panel RH	1	\$	1,140.40	\$	1,140.40	NDX	
98	Rear Side Inner Lower Panel LH	1	\$	1,140.40	\$	1,140.40	DDV	
99	Rear Side Air Vent RH	1	\$	86.30	\$	86.30	NDX	
100	Rear Side Air Vent LH	1	\$	86.30	\$	86.30	MIS	
101	Rear Side Railway End Garnish LH	1	\$	47.30	\$	47.30	NECV	
102	Rear Side Railway LH	1	\$	864.10	\$	864.10	BTV	
					Parts Sub Total :	\$	55,609.67	
					25% Discount	\$	13,902.42	
					PARTS TOTAL :	\$	41,707.25	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$		
1	Front Number Plate	1	\$	50.00	\$ 40.00 50.00	MIS
2	Front Bumper Clips - Set	1	\$	50.00	\$ 30.00 50.00	} NECV
3	Front Headlamp Assembly Clips - Set	1	\$	50.00	\$ 20.00 50.00	
4	Front Grille Clips - Set	1	\$	50.00	\$ 30.00 50.00	} NDI
5	Wiper Panel Garnish Clips - Set	1	\$	50.00	\$ 50.00	
6	Front Corner Panel Clips - Set	1	\$	30.00	\$ 30.00	} NDI
7	Front Dashboard Assembly Clips - Set	1	\$	50.00	\$ 50.00	
8	Front Windscreen Glass Sealant	1	\$	150.00	\$ 150.00	NDX
9	Front Bonnet Sealant	1	\$	150.00	\$ 150.00	} NDI
10	Front Support Panel Sealant	1	\$	150.00	\$ 150.00	
11	Front Dashboard Panel Sealant	1	\$	150.00	\$ 150.00	} NDI
12	Radiator Coolant	1	\$	60.00	\$ 40.00 60.00	
13	Rear Number Plate	1	\$	50.00	\$ 40.00 50.00	BRV
14	Rear Bumper Clips - Set	1	\$	50.00	\$ 30.00 50.00	NECV
15	Rear Taillamp Clips - Set	1	\$	40.00	\$ 20.00 40.00	NECV

16	Rear Tailgate Inner Trim Clips - Set	1	\$	40.00	\$ 20.00 40.00	NECV
17	Rear Tailgate Outer Garnish Clips - Set	1	\$	30.00	\$ 30.00	
18	Rear Side Panel Inner Trim Board Clips - Set	1	\$	80.00	\$ 30.00 80.00	NECV
19	Rear Tailgate Windscreen Glass Sealant	1	\$	150.00	\$ 40.00 150.00	NECV
20	Rear Tailgate "70km/h" Sticker	1	\$	40.00	\$ 20.00 40.00	V
21	Rear Tailgate Windscreen Glass Solar Film	1	\$	550.00	\$ 550.00	NNX
22	Rear Tailgate Sealant	1	\$	150.00	\$ 140.00 150.00	NECV
23	Rear End Panel Inner Sealant	1	\$	150.00	\$ 30.00 150.00	NECV
24	Rear End Panel Outer Sealant	1	\$	150.00	\$ 30.00 150.00	
25	Rear End Panel Side Sealant	2	\$	75.00	\$ 30.00 150.00	
26	Rear Floor Panel Sealant	1	\$	250.00	\$ 30.00 250.00	NECV
27	Rear Side Panel Outer Sealant	2	\$	150.00	\$ 300.00	
28	Rear Side Panel Inner Sealant	2	\$	150.00	\$ 300.00	
29	Rear Bumper Reverse Sensor - Set	1	\$	250.00	\$ 200.00 250.00	SCV
30	Rear Tailgate Reverse Camera	1	\$	550.00	\$ 550.00	NNX
				SPECIAL NETT TOTAL :	\$ 4,270.00	

Nos.	LABOUR	S\$	
1	To Panel Beat, Remove & Refix Parts (Front)	\$ 800.00 2,400.00	/
2	To Spray Paint Affected Areas (Front)	\$ 800.00 1,600.00	/
3	To Panel Beat, Remove & Refix Parts (Rear)	\$ 2,200.00 3,000.00	/
4	To Spray Paint Affected Areas (Rear)	\$ 1,200.00 2,000.00	/
5	Wiring & Bulb Check (Front)	\$ 100.00	NNX
6	Wiring & Bulb Check (Rear)	\$ 100.00	
7	To Remove & Refix Aircon Condenser And Top Up Gas	\$ 120.00 200.00	/
8	To Remove & Refix Radiator And Pressure Test	\$ 80.00 200.00	/
9	To Remove & Refix Air Cooler	\$ 200.00	NNX
10	To Remove & Refix Front Windscreen Glass	\$ 200.00	NNX
11	To Remove & Refix Dashboard Assembly	\$ 500.00	NNX
12	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 120.00 200.00	/
13	To Transfer Tailgate Mechanisms	\$ 80.00 150.00	/
14	To Remove & Refix Rear Bumper Reverse Sensor	\$ 60.00 150.00	/
15	To Remove & Refix Rear Tailgate Reverse Camera	\$ 250.00	NNX
16	To Remove & Refix Rear Exhaust Pipe	\$ 150.00	NNX
17	To Remove & Refix Rear Interior Upholstry to facilitate repairs	\$ 100.00 200.00	/
18	To apply anti rust on affected parts	\$ -250.00	NNX
19	To Conduct Water Leak Test	\$ 100.00	NNX
20	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00	
		LABOUR TOTAL :	\$ 12,430.00

survey & Resurvey
6/5/2022 TRUMBW

1500 hrs
Lump sum repair
Repair days 2.4

PARTS TOTAL :	\$	41,707.25
SPECIAL NETT TOTAL :	\$	4,270.00
LABOUR TOTAL :	\$	12,430.00
GRAND TOTAL :	\$	58,407.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer