

Ignite Motors Pte Ltd

1 Sin Ming Industrial Estate Sector C #01-117 Singapore 575636
Tel: 83831280

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : GBJ 3098Y
 Made : Toyota
 Model : Hiace
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate Windscreen Glass	1	\$ 1,254.20	\$ 1,254.20
Parts Sub Total :				\$ 1,254.20
25% Discount				\$ 313.55
PARTS TOTAL :				\$ 940.65

BRV

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Cabin Box	1	\$ 1,500.00	\$ 1,500.00
SPECIAL NETT TOTAL :				\$ 1,500.00

BRV

Nos.	LABOUR	S\$
1	To Remove & Refix Rear Cabin Box	\$ 300.00
LABOUR TOTAL :		\$ 300.00

BRV

Resurvey
18/5/2022
T. Chin Ann
1251 hrs

PARTS TOTAL : \$ 940.65
 SPECIAL NETT TOTAL : \$ 1,500.00
 LABOUR TOTAL : \$ 300.00
GRAND TOTAL : \$ 2,740.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____