



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22002354/Rty3n2-1	
			Date: 13/05/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 5114S	Veh. Inspected	PEQ 6382
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/03/22/2003	Excess (\$)	0.00
	Assign From	JOEY	Assign Date	27/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	PROTON WIRA	c.c	1298
	Engine No.	HIDDEN	Year of Reg.	2000
	Chassis No.	PL1C96LNRYB489153	Colour	GREY
	Odometer	332324 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	175/70 R13	DELIUM	6 mm
	L/H Front Tyre	175/70 R13	DELIUM	6 mm
	R/H Rear Tyre	175/70 R13	DELIUM	6 mm
	L/H Rear Tyre	175/70 R13	DELIUM	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/03/2022	Inspection Date	15/03/2022
	Survey held at	BLK 1 NO 387J WOODLANDS ROAD YEW TEE IND ESTATE		
	Repairer	ENG HUP AUTOPARTS ACCESSORIES CO.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	