



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                 |   |  |
|--|---|-----------------|---|--|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705  |   |                 | Ref: CS3/SMR22002354/Rty3-1               |  |
|  |   |                 | Date: <del>14/03/2022</del><br>27/04/2022 |  |
|  |   |                 | Code: SMR                                 |  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |   |                 |   |  |
| Insured Veh.   | SHB 5114S                                       | Veh. Inspected  | PEQ 6382                                  |  |
| Policy No.   |   | Coverage (\$)   | 0.00                                      |  |
| Claim No.  | TAX/03/22/2003                                  | Excess (\$)     | 0.00                                      |  |
| Assign From  | <del>HUA YEN</del> Joey                         | Assign Date     | 14/03/2022                                |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                 |   |  |
| Make & Model   |   | c.c             | 0   |  |
| Engine No.   | HIDDEN  | Year of Reg.    |   |  |
| Chassis No.  |   | Colour          |   |  |
| Odometer   | -   | Steering        |   |  |
| Brakes   |   | Modification    |   |  |
| General  |   |                 |   |  |
| <b>3. Conditions of Tyres</b>  |   |                 |   |  |
|  | Size  | Make            | Balance                                   |  |
| R/H Front Tyre   |   |                 | mm  |  |
| L/H Front Tyre   |   |                 | mm  |  |
| R/H Rear Tyre  |   |                 | mm  |  |
| L/H Rear Tyre  |   |                 | mm  |  |
| <b>4. Description of Damages</b>   |   |                 |   |  |
|  |   |                 |   |  |
| <b>5. General Information</b>  |   |                 |   |  |
| Accident Date  |   | Inspection Date | 15/03/2022                                |  |
| Survey held at   | Blk 1 NO 387J Woodlands Road YEW TEE IND ESTATE |                 |   |  |
| Repairer   | ENG HUP AUTOPARTS ACCESSORIES CO.               |                 |   |  |
| <b>5a. Remarks</b>   |   |                 |   |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                 |   |  |