

ASS. REC. BY: YML

REF:

CS3/SMR22002354/ y3

328M

ASSIGNMENT

CS3/SMR22002354/Rty3

Front

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: PEQ 6382at Workshop m/s ENH HUPof 3873 Yew Tee Indest

Insured:

SMR

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

10K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PEQ 6382

Yr Regn:

2000 / JulyType: (M.Cat) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

PROTON WIRA

c.c.

1298

Colour

GRAY

A/C:

Insured / Std / NI / NA

Sp. Reading

332324

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PLIC96LNR4B489153Gen. Cond: Good / (Fair) / Poor / BurntSteering: (In order) / Jammed / Leaked / Burnt orBrake: (In order) / Jammed / Leaked / Burnt orModl: Nil / (S/Rim) / STD A/Rim or

Tyre Size:

F:

175/70 R13

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DELUM

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/03/22

D.O.I.

15/03/22

Survey held at

ENH HUP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 5 days

SUBMIT PRS REPORT

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fees:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.R. (\$