

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

© /OptimaWerkz

Date: 05/05/2022

Vehicle No: SMN7635U

Model: TOYOTA WISH 1.8 CVT

Chassis: JTDGG20W80J002762-2015

Reg. Year: 2015

Third Party Insurer: MS FIRST CAPITAL

Third Party Veh No: SMB15735

Date of Accident: 05/05/2022

Estimator: TING AN

Surveyor:

*Not Notified
1/1 Rm & 2600h
Heavy Hitting
6 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>543.90</i>	1		<i>Br</i> \$595.00
2	REAR BUMPER SIDE BRACKET RH	1		<i>CM</i> \$95.00
3	REAR BUMPER REFLECTOR RH	1		<i>R</i> \$60.00
4	REAR TAIL LAMP RH	1		<i>Br</i> \$344.00
5	REAR TAIL LAMP LOWER BRACKET RH	1		<i>CM</i> \$55.00
6	REAR END PANEL	1		<i>R</i> \$536.00
7	REAR FENDER RH <i>921.60</i>	1		<i>R</i> \$955.00
8	REAR FENDER INNER TRIM BOARD RH	1		<i>R</i> \$750.00
9	REAR FENDER QUARTER GLASS RH <i>with mdy</i>	1		<i>mdy na</i> \$410.00
10	REAR TAILGATE	1		REPAIR
SUB TOTAL				\$3,800.00
LESS 25%				-\$950.00
PARTS TOTAL				\$2,850.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>na</i> \$50.00
2	REAR END PANEL JOINT SEALANT	1		<i>na</i> \$80.00
3	REAR FENDER QUARTER GLASS SEALANT RH	1		<i>na</i> \$80.00
4	REAR FENDER INNER TRIM BOARD CLIPS RH	1		<i>na</i> \$50.00
S/N TOTAL				\$260.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

600
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FENDER RH & ETC.

600
\$1,000.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

100
\$300.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 05/05/2022
Vehicle No: SMN7635U
Model: TOYOTA WISH 1.8 CVT
Chassis: JTDGG20W80J002762-2015
Reg. Year: 2015

Third Party Insurer: MS FIRST CAPITAL
Third Party Veh No: SMB1573S
Date of Accident: 05/05/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS RH, REAR FENDER GLASS SEALANT & ETC.

\$150.00 *601*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 *301*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 *201*

LABOUR TOTAL \$2,720.00

TING AN

TOTAL

\$5,830.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave. 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 680047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

