

**Section A - Accident Details**

Registration Number	SHC4723K
Case Reference Number	TAX/05/22/2005
Registration Date	4/3/2015
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WOON YONG CHIANG (YUN YONGQIANG)
Type of Accident	Head to Rear
Accident Date and Time	2/5/2022 8:12 PM
Accident Reported Date and Time	4/5/2022 11:37 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114806
Special Instruction to ARC, if any	TOWED \$40/ REAR PORTION
Prepared Date and Time	4/5/2022 1:19 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$200.00
Total Spray Cost	\$1,476.00	\$300.00
Total Spare Part Cost	\$4,401.91	\$861.46
Total Other Cost	\$436.00	(\$211.46)
<b>TOTAL COST</b>	<b>\$7,327.91</b>	<b>\$1,150.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	6.0	2.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Kenneth Kong (LKK)</b>
ARC / Surveyor Sign Off Date	<b>10/05/2022 5:18 PM</b>	<b>10/05/2022 4:20 PM</b>
Signature		
Remarks	Total number of repair days = 2 days. SUP = 0 day.	LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2205-0255	<b>Invoice Number</b>	
<b>Quotation Date</b>	23.05.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$200.00
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,476.00</b>	<b>\$300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$261.45)
<b>Total Other Costs</b>	<b>\$436.00</b>	<b>(\$211.45)</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	√
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace	√
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	√
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check	X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	X

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/06/2022

User ID : angbangklien

	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
	76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	✓
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Old Damage	X
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given	X
	68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	75442-47030	NAME PLATE (PRUIS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X
	75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
		STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>				<b>\$5,345.40</b>		<b>\$602.48</b>			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
<b>Total</b>					<b>345.30</b>		<b>258.98</b>		

	861.46	
+	200.00	
+	350.00	L/S \$1,150/-
	1,411.46	
	-20%	
	<u>1,129.17</u>	