



Case Details

Case Reference Number : TAX/05/22/2005
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4723K

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-18169-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 02/05/2022 12:12 PM
 Vehicle Age(In Months) : 86

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval		Remarks
													Repair/Replace	Remarks	
Standard	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	✓	Brc ✓
Standard	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	✓	Mn ✓
Standard	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓	Bn ✓
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓	Dis ✓
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓	n ✓
Standard	Main			ANTENNA ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	✓	nn
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	✓	pu x
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓	Dis ✓
Standard	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✓	nn
Standard	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Check	✓	pu x
Standard	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	✓	nn
Standard	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Check	✓	pu x
Standard	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	✓	nn
Standard	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.6	Replace	✓	Dis ✓

Total Spare Part Cost	4,142.94	Surveyor Total	602.48
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	3,297.07	Final Sur Total	481.98

Aspire 3

DDR4
Faster memory speed

Precision touchpad

802.11ac
Faster wireless

Intel® Celeron® processor N4020
Intel® UHD Graphics
4 GB DDR4 Memory

16:22 <https://vacswb.smrt.com.sg/estimation.aspx>

SMRT Recommendation											Surveyor Approval			
DOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	nn
Standard	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.93	Replace	0	0	Not Give	nn
Standard	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	rx
Standard	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.93	Replace	1	0	Old Darr	nn
Standard	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	nn
Standard	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give	nn
Standard	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	nn
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	0	0	Not Give	nn
Standard	Main			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	nn
Standard	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.93	Replace	0	0	Not Give	nn
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	nn
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	nn
Total Spare Part Cost									4,142.94	Surveyor Total		602.48		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,297.07	Final Sur Total		481.98		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	200	
Total:			1,014.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
4	Main	TO RESPRAY TAIL GATE	378.00	0	
Total:			1,296.00	200.00	