



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004216/Kvy3e2	
			Date: 10/06/2022	
			Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMR 3550K
	Policy No.	SP2000519021	Coverage (\$)	0.00
	Claim No.	2022 22004767/SL	Excess (\$)	2,000.00
	Assign From	Flora Quek	Assign Date	06/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72001023	Colour	METALLIC BLACK
	Odometer	176213 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	HABILEAD	6 mm
	L/H Front Tyre	185/60 R15	HABILEAD	6 mm
	R/H Rear Tyre	185/60 R15	HABILEAD	6 mm
	L/H Rear Tyre	185/60 R15	HABILEAD	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/05/2022	Inspection Date	09/05/2022
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE MARKET VALUE IS S\$91,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	