

REF:

AG-2/ 2200x2.01



FALCON - AIR AUTO SERVICES PTE LTD
Co. Reg. No. 1995011402
GST Reg. No. 1995011402

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897
ATTN: MOTOR CLAIMS DEPT
Attention : Motor Claim Department

Estimate : ES012387

Date : 06/05/2022
Vehicle Num.: SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng#: GP72001023
Accident Date : 05/05/2022
Claim No. :
Reference : O/D
Policy No. : SP2000519021

S/N	Quantity	Particular
-----	----------	------------

Unit Price	Amount S\$
------------	------------

- | QTY | DESCRIPTION | UNIT | PRICE | TOTAL |
|-----|--|------|-------|-------|
| 1 | 1 PC PARTS PURCHASED | | | |
| 2 | 1 PC FRONT WINDSCREEN GLASS | | | |
| 3 | 1 PC FRONT WINDSCREEN GLASS MOULDING TOP | | | |
| 4 | 1 PC FRONT WINDSCREEN GLASS MOULDING LOWER | | | |
| 5 | 2 PCS BONNET | | | |
| 6 | 1 PC BONNET HINGE | | | |
| 7 | 1 PC BONNET SEAL | | | |
| 8 | 1 PC BONNET LOCK | | | |
| 9 | 1 PC BONNET INSULATOR | | | |
| 10 | 2 PCS FRONT FENDER | | | |
| 11 | 1 PC FRONT WIPER PANEL GARNISH | | | |
| 12 | 1 PC AIR CLEANER DUCT | | | |
| 13 | 2 PCS AIR GUIDE | | | |
| 14 | 2 PCS HEADLAMP | | | |
| 15 | 2 PCS HEADLAMP CHROME | | | |
| 16 | 2 PCS HEADLAMP LOWER BRACKET | | | |
| 17 | 1 PC RADIATOR SUPPORT PANEL | | | |
| 18 | 1 PC RADIATOR AUTO | | | |
| 19 | 1 PC RADIATOR FAN COWLING | | | |
| 20 | 1 PC RADIATOR FAN MOTOR | | | |
| 21 | 1 PC RADIATOR FAN BLADE | | | |
| 22 | 1 PC RADIATOR HOSE TOP | | | |
| 23 | 1 PC AIR CON CONDENSER | | | |

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880/ 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 / No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg

branches

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D



LIANZ INSURANCE SINGAPORE PTE LTD
ROBINSON ROAD
19-01 068897
TN: MOTOR CLAIMS DEPT
ention : Motor Claim Department

Date : 06/05/2022
Vehicle Num. : SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng# : GP72001023
Accident Date : 05/05/2022
Claim No. :
Reference : O/D
Policy No. : SP2000519021

Quantity	Particular	Unit Price	Amount S\$
1 PC	FRONT NUMBER PLATE		45.00 ✓
16 PCS	FRONT BUMPER CLIP	3.00	48.00 ✓
Special Nett Total S\$:			164.00
LABOUR :			
	TO CHECK WIRING AND RE-FOCUS HEADLAMP		50.00 20l
	TO REMOVE/REFIX FRONT WINDSCREEN GLASS		150.00 120l
	TO VACUUM, REOIL AND REGAS AIR CON		120.00 100l
	TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS, INNER PANEL INCLUDING REPLACEMENT OF PARTS TO SPRAY PAINT ON BONNET, BONNET HINGES, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, RADIATOR SUPPORT PANEL, LH/RH FRONT FENDERS		750.00 600l
			1,600.00 1000l
Labour Total S\$:			2,670.00

Total S\$: 11,218.20

CON AIR AUTO SERVICES PTE LTD

on was prepared from visual inspection. Further materials and labour charges may be required when repair is completed. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997* No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg

Branches



FALCON-AIR

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897
ATTN: MOTOR CLAIMS DEPT
Attention: Motor Claim Department

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501149D
GST Reg. No.: 199501149D

Supplementary Estimate : ES012391

Date : 13/05/2022
Vehicle Num. : SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng# : GP72001023
Accident Date : 05/05/2022
Claim No. :
Reference : O/D
Policy No. : SP2000519021

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|------|-----------------------------|--|--|
| 1. | 1 PC | PARTS PURCHASED : | | |
| 2. | 1 PC | FRONT GRILLE TOP CHROME ✓ | | |
| 3. | 1 PC | FRONT GRILLE LOWER CHROME ✓ | | |
| | | TOW COVER ✓ | | |

cm 150.00 ✓
cm 110.00 ✓
cm 12.00 ✓

Total Parts Purchased S\$:
10.00% Of The Above Parts S\$:

272.00
27.20

Based On Cost Plus S\$:

299.20

PRIVATE HIRE STICKER ? ✓ m 18.69

E. & O.E.

Total S\$: 299.20

=====

FALCON AIR AUTO SERVICES PTE LTD

Quotation was prepared from visual inspection. Further materials and labour charges may be required when repair
nences. We will advise you accordingly.

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6453-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No 3 Pandan Loop (Blk 1/Blk K) S(128225) Tel: 6779-5665 Fax: 6779-1110