



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No. Page 1/3
GST Reg. No. 1995011400

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01 068897

ATTN: MOTOR CLAIMS DEPT

Attention : Motor Claim Department

Estimate : ES012387

Date : 06/05/2022

Vehicle Num. : SMR 3550K

Make/Model : HONDA SHUTTLE HYBRID-2018/2019

Chassis/Eng# : GP72001023

Accident Date : 05/05/2022

Claim No. :

Reference : O/D

Policy No. : SP2000519021

Not Authorized
Running B4paim
7 days
6x \$2000

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PARTS PURCHASED :

1.	1 PC	FRONT WINDSCREEN GLASS	CM	1,100.00	✓
2.	1 PC	FRONT WINDSCREEN GLASS MOULDING TOP	RM	30.00	✓
3.	1 PC	FRONT WINDSCREEN GLASS MOULDING LOWER	RM	40.00	✓
4.	1 PC	BONNET	RM	600.00	✓
5.	2 PCS	BONNET HINGE	0/1 ?	35.00	✓
6.	1 PC	BONNET SEAL	ALSDIR	70.00	✓
7.	1 PC	BONNET LOCK	WT	25.00	✓
8.	1 PC	BONNET INSULATOR	ORT	100.00	✓
9.	2 PCS	FRONT FENDER	SM	90.00	X
10.	1 PC	FRONT WIPER PANEL GARNISH	OLSR	160.00	✓
11.	1 PC	AIR CLEANER DUCT	ALSR	165.00	✓
12.	2 PCS	AIR GUIDE	RM	48.00	X
13.	2 PCS	HEADLAMP	my CM	25.00	✓
14.	2 PCS	HEADLAMP CHROME	500.00	1,000.00	✓
15.	2 PCS	HEADLAMP LOWER BRACKET	65.00	130.00	✓
16.	1 PC	RADIATOR SUPPORT PANEL	45.00	90.00	✓
17.	1 PC	RADIATOR AUTO	RM	500.00	✓
18.	1 PC	RADIATOR FAN COWLING	800.00	✓	✓
19.	1 PC	RADIATOR FAN MOTOR	CM	75.00	✓
20.	1PC	RADIATOR FAN BLADE	230.00	✓	✓
21.	1 PC	RADIATOR HOSE TOP	40.00	✓	✓
22.	1 PC	AIR CON CONDENSER	SM	30.00	X
				500.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

FALCON - AIR

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897

ATTN: MOTOR CLAIMS DEPT

Attention : Motor Claim Department

Estimate : ES012387

Date : 06/05/2022

Vehicle Num. : SMR 3550K

Make/Model : HONDA SHUTTLE HYBRID-2018/2019

Chassis/Eng# : GP72001023

Accident Date : 05/05/2022

Claim No. :

Reference : O/D

Policy No. : SP2000519021

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	RADIATOR SUPPORT PANEL TOP GARNISH	Dis 55.00	✓
24.	1 PC	AIR CON FAN MOTOR	230.00	✓
25.	1 PC	AIR CON FAN COWLING	75.00	✓
26.	1 PC	AIR CON FAN BLADE	40.00	✓
27.	1 PC	FRONT GRILLE	cm 280.00	✓
28.	1PC	FRONT GRILLE LOGO	m 30.00	✓
29.	1 PC	FRONT GRILLE TOP HOLDER	25.00	✓
30.	1 PC	FRONT BUMPER	Am 400.00	✓
31.	2 PCS	FRONT BUMPER SIDE RETAINER	12.00 Drt 24.00	✓
32.	1 PC	FRONT BUMPER REINFORCEMENT	Rt 185.00	✓
33.	1 PC	FRONT BUMPER LOWER GRILLE	Dr't 40.00	✓
34.	1 PC	RH FRONT BUMPER GARNISH	30.00	✓
35.	1PC	OUTSIDE TEMPERATURE SENSOR	70.00	✓
36.	1 PC	LH WIPER GARNISH CORNER	cm 35.00	✓
37.	2 PCS	HYBRID LOGO	35.00 m 70.00	✓
Total Parts Purchased S\$:			7,622.00	
10.00% Of The Above Parts S\$:			762.20	
Based On Cost Plus S\$:			8,384.20	
SPECIAL NETT ITEMS :				
1.	1 PC	WINDSCREEN GLASS SEALANT	m 45.00	✓
2.	1 PC	ERP BRACKET	m 26.00	✓

CONTINUE / ...



FALCON-AIR

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 068897
ATTN: MOTOR CLAIMS DEPT
Attention : Motor Claim Department

FALCON - AIR AUTO SERVICES PTE LTD
Page 3/3
Co. Reg. No. 199501140D
GST Reg. No. 199501140D

Estimate : ES012387

Date : 06/05/2022
Vehicle Num. : SMR 3550K
Make/Model : HONDA SHUTTLE HYBRID-2018/2019
Chassis/Eng# : GP72001023
Accident Date : 05/05/2022
Claim No. :
Reference : O/D
Policy No. : SP2000519021

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1 PC	FRONT NUMBER PLATE		45.00 ✓
4.	16 PCS	FRONT BUMPER CLIP	3.00	48.00 ✓
Special Nett Total S\$:				164.00
LABOUR :				
TO CHECK WIRING AND RE-FOCUS HEADLAMP				50.00 201
TO REMOVE/REFIX FRONT WINDSCREEN GLASS				150.00 1201
TO VACUUM, REOIL AND REGAS AIR CON				120.00 1001
TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS, INNER PANEL INCLUDING REPLACEMENT OF PARTS				750.00 6001
TO SPRAY PAINT ON BONNET, BONNET HINGES, FRONT BUMPER, FRONT BUMPER REINFORCEMENT, RADIATOR SUPPORT PANEL, LH/RH FRONT FENDERS				1,600.00 10001
Labour Total S\$:				2,670.00

E. & O.E.

Total S\$: 11,218.20
=====


for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.