

ASS. REC. BY:

REF: INC / NS/INC22004217/Ktc

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s SMART

of _____

Insured: _____

Policy No. _____


Claims No. MT/1170951-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 6093B Yr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Maroon Colour: Maroon c.c. 1798Sp. Reading: 477384 A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U 405 768492Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Skilun

Front

Rear

R/Bal. 4 mmR/Bal. 8 mmL/Bal. 4 mmL/Bal. 8 mmD.O.A. 3/5/22D.O.I. 4/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

advise principle the repair cost of \$950.00, 3days,

red: 4885.49; 83%

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Parking

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Case Details

Case Reference Number :

TAX/05/22/2007

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6093B

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18174-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 03/05/2022 12:13 PM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace ▾	BENT
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace ▾	NEC
Standard	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give ▾	NN
Standard	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace ▾	DIS
Standard	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give ▾	nn
Standard	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give ▾	NN
Standard	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give ▾	NN
Standard	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give ▾	NN
Standard	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0	Not Give ▾	NN
Standard	Main			DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0	Not Give ▾	NN
Standard	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give ▾	NN
Standard	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give ▾	NN
Standard	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give ▾	NN

Total Spare Part Cost 5,216.33

Lump Sum Discount (%) 20.00

Surveyor Total 491.47

Lump Sum Dis (%) 20

Type	Costing Type	Portion	Material Number	SMRT Recommendation					Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	NN
Standard	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give	NN
Standard	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0	Not Give	NN
Standard	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0	Not Give	NN
Standard	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give	NN
Standard	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Check	NN
Standard	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	NN
Standard	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	NN
Standard	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	NN
Standard	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	0	0	Not Give	NN
Standard	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	NN
Standard	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	NN
Standard	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	NN
Standard	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give	NN
Standard	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	NN
Standard	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Check	NN
Standard	Main			SUPPORT RADIATOR, LH	1	17.70	17.70	25.00	13.27	Replace	0	0	Not Give	NN
Standard	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair	
Standard	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.93	Replace	1	38.93 38.92	Replace	NEC
Standard	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	NN
Standard	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Not Give	NN
Standard	Main			SEAL, FRONT FENDER TO COWL SIDE LH	1	15.20	15.20	25.00	11.40	Replace	0	0	Not Give	NN

Total Spare Part Cost 5,216.33

Surveyor Total 491.47

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,143.49

Final Sur Total 393.18

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	▼
Standard	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	▼
Total Spare Part Cost									5,216.33	Surveyor Total			491.47	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									4,143.49	Final Sur Total			393.18	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	676.00	300	
Total:			676.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:			756.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			260.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,143.49	393.18
Total Labour Cost	676.00	300.00
Total Spray Painting	756.00	400.00

Estimator Assessment(\$)

260.00

Overall Total

5,835.49

Lump Sum Repair Option



Lump Sum Total

5,850.00

Surveyor Approved Amount

No of Repair Days*

6

Remarks

-

Surveyor Name

Signature

Surveyor Assessment(\$)

0.00

1,093.18



1,100.00

1,100.00

3

LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK
ITEM and REPLACE ITEM PLEASE CALL SURVEYOR
Kenneth Kong (LKK) HP : 9691 0663 / Email :

Kenneth Kong (LKK)

Save

Clear

Survey Date

04/05/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/05/2022 15:53 (SGT)
Date of Accident	03/05/2022 20:13 (SGT)
Exact Location of Accident	2 Jurong East Street 21, Singapore 609601
Additional Location Information	IMM CAR PARK JURONG EAST ST 21
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6093B
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

DRIVER

Name of Driver	RUSLI BIN SHAHDAN
NRIC No	SXXXX108D

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or printed text on the paper.

We declare the foregoing particulars are true in every respect.



Driver's Signature (If driver is not the policy holder) John
& Time

4.6.2022