


STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/05/2022
User ID : PohSuan
Section A - Accident Details

Registration Number	SHD6093B
Case Reference Number	TAX/05/22/2007
Registration Date	27/7/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	RUSLI BIN SHAHDAN
Type of Accident	Head to Rear
Accident Date and Time	3/5/2022 8:13 PM
Accident Reported Date and Time	4/5/2022 12:28 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114807
Special Instruction to ARC, if any	TP/FRONT LEFT PORTION/NTUC - LKK
Prepared Date and Time	4/5/2022 4:02 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$5,216.33	\$491.48
Total Other Cost	\$260.00	(\$241.48)
TOTAL COST	\$6,908.33	\$950.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / NTUC
ARC / Surveyor Sign Off Date	04/05/2022 5:20 PM	04/05/2022 4:56 PM
Signature		
Remarks	LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2205-0155	Invoice Number	
Quotation Date	17.05.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$241.48)
Total Other Costs	\$260.00	(\$241.48)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Not Given
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Not Given
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given
		52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given

✓
✓
X
✓
X
X
X
X
X
X
X
X
X
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/05/2022

User ID : PohSuan

		81521-47050	LENS & BODY,FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X
		75310-47010	EMBLEM FRONT	0.00	\$86.50	0.00	\$0.00	Replace	Not Given	X
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X
		53113 - 47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
		51444-12050	UNDER COVER SIDE/LH	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check	X
		16534-37010	SUPPORT RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Not Given	X
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	R
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	√
		53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
		53828-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Not Given	X
		53867-47030	SEAL, FRONT FENDER TO COWL SIDE LH	0.00	\$15.20	0.00	\$0.00	Replace	Not Given	X
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
		53852-47020	FENDER LINER PAD, FR WHEEL, LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
Total					\$6,499.10		\$491.48			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	491.48	
+	300.00	L/S \$950/-
+	400.00	
	<u>1,191.48</u>	
	-20%	
	<u>953.18</u>	