

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004218/UVY3N2**Date:** 10/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00118312100

Claimant Vehicle No : SJS5019X **Insured Vehicle No :** SJU3898C

Date of Loss: 05/05/2022 Nature of Claim: TP Claim No: SNM22D203083/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS5019X**

Make & Model: KIA CERATO FORTE, 1.6 EX (A) Engine No: G4FC9H275051

Reg. Date: 20/08/2009 (Man. Year: 2009) Chassis No: KNAFU411LA5101130

Colour: Brown Odometer: 179732 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45ZR17 Rear Tyre Size: 215/45ZR17

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,594.00	1,163.90	430.10	26.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	750.00	1,000.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,344.00	1,913.90	1,430.10	42.77
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	3,344.00	1,500.00	1,844.00	55.14
+ GST 7.00/7.00% (\$\$)	234.08	105.00	129.08	55.14
Nett Amount (\$\$)	3,578.08	1,605.00	1,973.08	55.14

INSPECTION

Date of Assignment: 09/05/2022

Date Inspected: 25/05/2022 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	143	KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS5019X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	688.00 F	*688.00 FL
2	4		*REAR BUMPER CLIP	Necessary	14.00 F	*14.00 FL
3	1		*REAR BUMPER LOWER GARNISH	Grazed	241.00 F	*241.00 FL
4	1		*REAR BUMPER SPONGE	Torn	304.00 F	*128.00 FL
5	1		*BOOTLID EMBLEM	Not Necessary	41.00 F	*- FL
6	1		*BOOTLID LOGO-CERATO FORTE	Not Necessary	26.00 F	*- FL
7	1		*BOOTLID LOGO-C&C (NPA)	Not Necessary	0.00 F	*- FL
8	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
9	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS
10	1		*BOOTLID (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,594.00	1,271.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	107.10
Total Parts (\$\$)	1,594.00	1,163.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	400.00
3	ANTI-RUST COATING	New	100.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			1,750.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >