



Case Details

Case Reference Number :
TAX/05/22/2003

Type of Repair : Accident Repair

Vehicle Registration Number :
SHB5775J

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18168-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 02/05/2022 04:45 AM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Not Give	
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	
Standard	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	0	0	Not Give	
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give	
Standard	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	
Standard	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	
Standard	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	
Standard	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	
Standard	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	0	0	Not Give	

Total Spare Part Cost 3,391.72
Lump Sum Discount (%) 20.00
Final Spare Part Cost 2,713.38

Surveyor Total 0.00
Lump Sum Dis (%) 20
Final Sur Total 0.00

COM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Give	▼
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give	▼
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	▼
Standard	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give	▼
Standard	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	▼
Standard	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	▼
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Give	▼
Total Spare Part Cost									3,391.72	Surveyor Total		0.00		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									2,713.38	Final Sur Total		0.00		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0	
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			738.00	200.00	

Other Cost Detail

	Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			380.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,713.38	0.00
Total Labour Cost	676.00	200.00
Total Spray Painting	738.00	200.00
Other	380.00	0.00
Overall Total	4,507.38	400.00
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,500.00	400.00
Surveyor Approved Amount		400.00
No of Repair Days*	4	2
Remarks		LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email :
Surveyor Name		Kenneth Kong (LKK)
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>

Survey Date

04/05/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/05/2022 14:31 (SGT)
Date of Accident	02/05/2022 12:45 (SGT)
Exact Location of Accident	Ang Mo Kio, Singapore
Additional Location Information	ANG MO KIO AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5775J
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY


Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

DRIVER

Name of Driver	PANG KIN HUNG
NRIC No	SXXXX622C

Describe Circumst

I am driving on AMK AVE 1 toward CTE from Amk Ave 8, the traffic Light turn amber before last Arrow on the ground. I slow down and stop. Driver of SLT 7891B ~~unable to stop down~~ from behind ~~being~~ in hit my back of my Taxi



Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time

Alan
 Driver's Signature (if driver is not the policyholder) / Date & Time
 4/May/2022

Mr 4.5.2022
 Witnessed by Reporting Centre Personnel