

Not Noted
 11 By 83050h
 Recovery After Repair
 6 days

VEHICLE NO: GBF7681H
 CHASSIS NO: W0L6WYL11G9593832

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
PARTS (LIST ITEMS)	
TAILGATE DOOR LHS	RH \$ 1,600.00 ✓
TAILGATE DOOR RHS	N/C (RH) \$ 1,600.00 X
TAILGATE DOOR LOCK ASSY	\$ R 240.00 X
TAILGATE DOOR UPPER HINGE LHS	\$ R 100.00 X
TAILGATE DOOR LOWER HINGE LHS	\$ R 100.00 X
TAILGATE DOOR WINDSCREEN MOULDING LHS	\$ R 160.00 ✓
TAILGATE DOOR WINDSCREEN MOULDING RHS	\$ R 160.00 X
TAILGATE DOOR INNER TRIM LHS	\$ R 600.00 X
REAR BUMPER	RH \$ 560.00 ✓
REAR BUMPER RETAINER LHS	\$ R 70.00 X
REAR BUMPER RETAINER RHS	\$ R 70.00 X
REAR BUMPER LOWER COVER	\$ R 200.00 ✓
"COMBO" EMBLEM	\$ R 60.00 ✓
TAIL LAMP LHS	\$ R 200.00 X
END PANEL	\$ R 240.00 X
END PANEL TOP GARNISH	\$ R 160.00 ^
FLOOR BOARD	\$ R 1,200.00 X
TAILGATE DOOR WEATHERSTRIP	\$ R 200.00 X
REAR REINFORCEMENT 400	\$ R 440.00 ✓
TAIL LAMP LHS	\$ R 350.00 X
	\$ 8,310.00
10%	\$ 831.00
	\$ 7,479.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SPECIAL NETT ITEMS

REAR BUMPER CLIPS 1 SET
REAR SENSORS
70KM/HR STICKER

Me \$ 100.00
Su \$ 200.00
Me \$ 30.00

50

12

\$ 330.00

\$ 7,809.00

TOTAL PARTS & LAB

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
LABOUR			
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,800.00	400
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20
4	To provide anti-rust treatment on affected areas	\$ 100.00	30
5	Transfer front door parts LHS & RHS	\$ 300.00	200 X
6	Transfer tailgate door parts LHS & RHS	\$ 300.00	200
7	Remove and refit rear windscreen LHS & RHS	\$ 300.00	60
Labour Total :		\$ 4,700.00	
TOTAL (PARTS & LABOUR):		\$ 12,509.00	