

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427844N

TO : AXA DATE 05/05/2022
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE T/ P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SJM9427G

MODEL : HONDA FIT 1.3G A

CHASSIS NO

ACCIDENT DETAILS DATE : 4-May-22
TIME : 05:55HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No dispute mediation is allowed
- Vehicle must be resurveyed and approved by Insurance Company

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Deformed</i>	1	\$ 788.90	\$ 788.90
2	TAIL GATE LOGO <i>Neu</i>	1	\$ 45.90	\$ 45.90
3	TAIL GATE EMBLEM "JAZZ" <i>Neu</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE INNER LOCK <i>Deformed</i>	1	\$ 198.20	\$ 198.20
5	TAIL GATE CATCH <i>Neu</i>	1	\$ 55.70	\$ 55.70
6	TAIL GATE WEATHER STRIP <i>lt</i>	1	\$ 102.00	\$ 102.00
7	TAIL GATE INNER TRIM <i>Deformed</i>	1	\$ 153.50	\$ 153.50
8	TAIL GATE WINDSCREEN MOULDING <i>Neu</i>	1	\$ 97.10	\$ 97.10
9	REAR BUMPER <i>Deformed</i>	1	\$ 555.30	\$ 555.30
10	REAR BUMPER SIDE RETAINER <i>LH Neu</i>	2	\$ 64.50	\$ 129.00
11	TAIL LAMP LH <i>lt</i>	1	\$ 266.50	\$ 266.50
12	TAIL LAMP BRACKET LH <i>Neu</i>	1	\$ 48.00	\$ 48.00
13	TAIL LAMP PANEL LH <i>Deformed</i>	1	\$ 155.60	\$ 155.60
14	REAR FENDER LH <i>Regis</i>	1	\$ 820.50	\$ 820.50
15	REAR FENDER INNER TRIM LH <i>crushed</i>	1	\$ 290.20	\$ 290.20
16	REAR END PANEL <i>Distorted</i>	1	\$ 355.90	\$ 355.90
17	REAR END PANEL TOP GARNISH <i>Deformed</i>	1	\$ 94.20	\$ 94.20
18	TOOLS SPONGE <i>torn</i>	1	\$ 188.30	\$ 188.30
19	REAR FLOOR PANEL <i>Regis</i>	1	\$ 799.80	\$ 799.80

20	REAR FLOOR PANEL TOP BOARD <i>Nol New</i>	1	\$ 265.00	\$ 265.00	<i>f.</i>
----	---	---	-----------	-----------	-----------

332070
2656.56

TOTAL PRICE \$ 5,449.60
LESS 20% \$ 1,089.92
SUB TOTAL PRICE \$ 4,359.68

2680.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Nol New</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	TAIL GATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
3	TAIL GATE WINDSCREEN SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	<i>60</i>
4	REAR BUMPER CLIP <i>New</i>	1	\$ 22.00	\$ 22.00	<i>✓</i>
5	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
6	REAR FENDER INNER TRIM CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
8	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 120.00	\$ 120.00	<i>60</i>
9	REAR FLOOR PANEL INSULATION SEAL <i>Nol New</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
10	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

412

TOTAL \$ 832.00

412

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	1000	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	1000	
3	TRANSFER TAILGATE MECHANISM	\$ 80.00	60	
4	TUFF COAT	\$ 250.00	60	
5	WIRING CHECK	\$ 100.00	30	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50	
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	50	

TOTAL

\$3,650.00

2370

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,191.68

TOTAL LABOUR COST : \$ 3,650.00

Rel 5438.56
H/S 14350

Adnan L
4/5 09/05/22

07 Days

2370