

ASSIGNMENT

From:

Date

Estimated Cost:

Veh No:

SHA10826

Yr Regn:

29/6/17

Type: M.Car / M.Cycle / Bus / Van / Lorry /

☒ Taxi / Prime Mover /

COMFORT DELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

VEHICLE NO SHA4505J

MAKE REG 13.10.2016

35.05.2022

MODEL HYU-140

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER LOWER COVER			\$228.00
2	REAR BUMPER BRACKET SIDE /RH			\$35.60
10	REAR BUMPER CLIPS		\$35.60	\$356.00
1	TAIL LAMP RH		\$2.20	\$22.00
1	REAR WHEEL CAP			\$697.80
1	REAR FENDER RH			\$214.20
				\$2,171.40
				\$3,922.00
	20.00% DISCOUNTED TOTAL			\$784.40
				\$3,137.60
1	REAR FENDER ADVERTISEMENT			\$100.00
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REAR BUMPER MAT			\$50.00
1	REVERSE SENSOR			\$135.70
				\$335.70
	Labour Charge			
	Panel Beating			\$850.00
	Spray Painting Charge			\$600.00
	Remove/Refix Upholstery			\$90.00
	Check lighting			\$60.00
	Tuff Kote			\$90.00
	TOTAL LABOUR			\$1,690.00
	ESTIMATE TOTAL			\$5,163.30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan

82235769

6/5/22 1636

C/S 3 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: