



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22004227/Uga3q2 Date: 20/07/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMG 9891U	Veh. Inspected	SKB 6140Z
	Policy No.	P2231298	Coverage (\$)	0.00
	Claim No.	S2M03ZXB	Excess (\$)	0.00
	Assign From		Assign Date	04/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ C 180 (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WDD2040452A552635	Colour	SILVER
	Odometer	211964 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	PIRELLI	6 mm
	L/H Front Tyre	225/45 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/45 R17	PIRELLI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	29/04/2022	Inspection Date	17/05/2022
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	