

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

13-06-22

Date Of Accident : 29-04-2022

OUR REF : SKB 6140Z/T/22

Thia Lee Kiow

213 Bedok South Ave 1

#04-19

Singapore 469337

*not allowed  
L/s \$3700  
4 days  
17/5/22*

*LKK - Mercedes (SJB)*

*Date In/out:*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 17/05/22 to 22/05/22

## ESTIMATE BILL ON VEH. NO. : SKB 6140Z

MODEL : MERCEDES BENZ C180

CHASSIS NO.: WDD2040452A552635

### LIST ITEM

|                                       |               |                    |            |
|---------------------------------------|---------------|--------------------|------------|
| Rear Bumper                           | 1631          | Re/Toon            | 1,899.00   |
| Rear Bumper Side Retainer LH          |               | 11                 | 45.00 X    |
| Rear Bumper Clips                     | 10pcs @ 4.50  | 11                 | 45.00      |
| Rear Bumper Chrome Moulding (RH & LH) | 2pcs @ 136.00 | 11                 | 272.00     |
| Rear Bumper Chrome Moulding (Center)  |               | 11                 | 195.00     |
| Rear Lower Arm LH                     |               | 11                 | 540.00 X   |
| Rear Knuckle Arm LH                   |               | 11                 | 1,652.00 X |
| Rear Wheel Bearing Hup                |               | Daye               | 580.00     |
| Rear Upper Arm                        |               | 11                 | 455.00 X   |
| Sport Rim Assy                        |               | 11                 | 960.00     |
|                                       |               |                    | 6,643.00   |
|                                       | 3683          | Less Discount 10%: | 664.30     |
|                                       |               |                    | 5,978.70   |

### LABOUR CHARGE

|                                                                               |                       |                 |
|-------------------------------------------------------------------------------|-----------------------|-----------------|
| To Check & Adjust Computer Wheel Alignment (Before & After)                   | 100                   | 240.00          |
| To Remove & Refix Rear LH Undercarriage                                       | 150                   | 280.00          |
| To Remove & Refix Rear LH Sport Rim & Contact Wheel Bearing                   |                       | 120.00          |
| To Respray Affected Areas                                                     | 400                   | 500.00          |
| To Renew Damaged Parts, Straighten & Renew Rear LH Fender & Aligned All Parts | 300                   | 480.00          |
|                                                                               |                       | 7,598.70        |
|                                                                               | GST 7%:               | 531.91          |
|                                                                               | <b>TOTAL AMOUNT :</b> | <b>8,130.61</b> |