

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

FD21402044

04 May 2022

QUOTATION FOR ACCIDENT REPAIR OF SML892A HONDA CIVIC TYRE R

THIRD PARTY INSURER: AXA INSURANCE

S/No.	Parts List	Qty	Amount (\$)
1.	Rear boot lid <i>Regis</i>	1	\$ 796.00 +
2.	Rear boot lid "logo" emblem (Red) <i>3 new</i>	1	\$ 65.40 -
3.	Rear boot lid "Tyre R" emblem	1	\$ 95.00 -
4.	Rear boot lid reflector lamp RH <i>cut</i>	1	\$ 280.40 -
5.	Rear boot lid weather strip <i>new</i>	1	\$ 157.60 +
6.	Rear bumper <i>Distorted</i>	1	\$ 1568.50 960.
7.	Rear bumper diffuser <i>Crushed</i>	1	\$ 974.30 567
8.	Rear bumper diffuser lower <i>torn</i>	1	\$ 268.40 ✓
9.	Rear bumper diffuser upper <i>new</i>	1	\$ 325.90 +
10.	Rear bumper side retainer L/R <i>RH 2nd</i>	2	\$ 93.20 35.
11.	Rear taillamp RH <i>crushed</i>	1	\$ 640.40 340
12.	Rear taillamp lower bracket RH <i>Best</i>	1	\$ 44.20 25.
13.	Rear taillamp panel RH <i>Distorted</i>	1	\$ 186.00 ✓
14.	Rear end panel <i>Distorted</i>	1	\$ 392.60 ✓
15.	Rear end panel garnish <i>Distorted</i>	1	\$ 140.40 ✓
16.	Rear fender RH <i>Buckled</i>	1	\$ 890.70 ✓
17.	Rear fender inner shield RH <i>torn</i>	1	\$ 110.30 -
18.	Rear fender air vent RH <i>crushed</i>	1	\$ 77.00 -
19.	Rear fender inner trim RH <i>crushed</i>	1	\$ 428.00 325
20.	Rear windscreen moulding <i>new</i>	1	\$ 157.20 -
21.	Rear upper arm RH <i>3</i>	1	\$ 446.00 +
22.	Rear trailing arm RH <i>3 new</i>	1	\$ 475.20 +
23.	Rear wheel bearing RH	1	\$ 255.50 +
24.	Rear knuckle RH	1	\$ 430.40 +
Subtotal before discount			\$ 9298.60
Discount 20%			\$ 1859.72
Subtotal 1			\$ 7438.88

46.60

491540

3932.32

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103/ 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

04 May 2022

QUOTATION FOR ACCIDENT REPAIR OF SML892A HONDA CIVIC TYRE R THIRD PARTY INSURER: AXA INSURANCE

<u>S/NETT</u>	<u>Parts List</u>	<u>Qty</u>	<u>Amount (\$)</u>
1.	Rear windscreen sealant <i>new</i>	1	\$ 80.00 <i>60</i>
2.	Rear reverse camera <i>new</i>	1	\$ 400.00 <i>+</i>
3.	Rear reverse sensor <i>new</i>	1	\$ 350.00 <i>+</i>
4.	Rear bumper clip <i>new</i>	1	\$ 30.00 <i>+</i>
5.	Rear end panel garnish clip <i>new</i>	1	\$ 30.00 <i>10</i>
6.	Rear fender inner trim board clip RH	1	\$ 30.00 <i>430</i>
7.	Rear tyre RH <i>new</i>	1	\$ 350.00 <i>+</i>
8.	Rear sport rim RH <i>lot</i>	1	\$ 400.00 <i>300</i>
9.	Rear shock absorber RH <i>new</i>	1	\$ 600.00 <i>+</i>
S/Nett Total			\$ 2270.00

LABOUR

To check wirings.	\$ 80.00 <i>30</i>
To remove and reinstall rear windscreen	\$ 150.00 <i>120</i>
To remove and reinstall rear interior trims, garnish, seats etc	\$ 180.00 <i>60</i>
To remove and replace, refix undercarriage	\$ 350.00 <i>+</i>
To conduct 4 wheel alignment	\$ 120.00 <i>80</i>
To remove and refix rear reverse sensor	\$ 120.00 <i>50</i>
To spray anti-rust coating on new and affected panel	\$ 120.00 <i>100</i>
To straighten, repair, realign on rear affected area and replace damaged parts	\$ 1200.00 <i>1000</i>
To spray painting on affected area	\$ 1200.00 <i>1000</i>
Total Labour Cost	\$ 3520.00

Total: 680232
4/5: 5.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
4/5 04/05/22
08 Days.