

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0372/2022/JT
DATE : 11-May-22
WIP : 23034

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 12/5/22

YOUR INSURED VEH NO : SND 8529 C

FWD INSURANCE SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

Attn: Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

OWNER'S NAME : MR CHAI CHEW YIAN
ADDRESS : 13 TOH YI DR
#10-21
SINGAPORE 590013
TELEPHONE : HP +65 96228158
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100488592-05
VEHICLE NO : **SGU 5477 G**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 28/10/2016
ENGINE NO : CZC 558920
CHASSIS NO : WAUZZZ8V6G1101952
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-May-22
PLACE OF ACCIDENT : TOA PAYOH CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGU 5477 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	
4	TO RESPRAY FRONT BUMPER.	\$ 900.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,852.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGU 5477 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 195.00	
3	FRONT BUMPER TRIM COVER - RH	1	\$ 182.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 175.00	
5	FRONT BUMPER PULL STRAP - LOWER	4	\$ 231.00	
6	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 122.00	
8	RADIATOR GRILLE	1	\$ 765.00	
9	RADIATOR GRILLE COVER - UPPER	1	\$ 109.00	
10	CAUTION STICKER	1	\$ 16.00	
11	AIR COND STICKER	1	\$ 9.00	
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 847.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 154.00	
14	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 63.00	
15	RADIATOR AIR GUIDE - RH	1	\$ 28.00	
16	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 14.00	
17	HEADLIGHT - RH	1	\$ 2,810.00	
18	LIFT CYLINDER - RH	1	\$ 211.00	
19	LIFT CYLINDER HOSE - RH	1	\$ 204.00	
20	FRONT NO PLATE	S/N	\$ 60.00	
21	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 8,915.00	
TOTAL LABOUR CHARGES		:	\$ 2,852.00	
GRAND TOTAL		:	\$ 11,767.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT