



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206619

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 26/10/2022
Reference CC6/CTI22004234/Rpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMX 2929C
Insured Veh. GBH 6409A
Claim No. SNM22D202983/C02
Policy No. DMCVSNW00009952200
Accident Date 02/05/2022
Inspection Date 24/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22004234/Rpa3q2 Date: 26/10/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 6409A	Veh. Inspected	SMX 2929C	
Policy No.	DMCVSNW00009952200	Coverage (\$)	0.00	
Claim No.	SNM22D202983/C02	Excess (\$)	0.00	
Assign From		Assign Date	24/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180 AV	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2050402R341795	Colour	BLUE	
Odometer	81330 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	MICHELIN	6 mm	
L/H Front Tyre	225/50 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/05/2022	Inspection Date	24/05/2022	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 2929C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	SCRATCHED	1,800.00	1,800.00
4	FRONT BUMPER CLIP @\$10.00	NECESSARY	40.00	40.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	180.00	-
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	60.00	-
1	FRONT BUMPER SIDE GRILLE RH	CUT	120.00	120.00
1	FRONT BUMPER BASIC CARRIER RH	NOT NECESSARY	100.00	-
1	FRONT BUMPER IMPACT ABSORBER	NOT NECESSARY	220.00	-
1	FRONT BUMPER UPPER RUBBER SEAL	NOT NECESSARY	50.00	-
1	HEAD LAMP UNIT RH	SCRATCHED	3,800.00	3,800.00
1	FRONT REINFORCEMENT	NOT NECESSARY	480.00	-
1	FRONT REINFORCEMENT BRACKET RH	NOT NECESSARY	250.00	-
1	FRONT DISTANCE SENSOR WIRING HARNESS	NOT NECESSARY	200.00	-
1	FRONT DISTANCE SENSOR BUMPER OUTER RH	SCRATCHED	240.00	240.00
2	FRONT DISTANCE SENSOR DECOUPLING RING @\$10.00	NECESSARY	20.00	20.00
1	FRONT DISTANCE SENSOR BUMPER INNER RH	NOT WORKING	240.00	240.00
1	FRONT CROSSMEMBER BRACKET RH (ADDITIONAL)	CRACKED	120.00	120.00
	LESS 10% DISCOUNT		-	-638.00
			7,920.00	5,742.00
	<u>LABOUR</u>			
	SPRAY PAINT FRONT BUMPER ,FENDER RH AND BONNET .		800.00	600.00
	REMOVE,REFIT ,REPAIR AND REPLACE ACCIDENT AFFECTED PARTS.		800.00	400.00
	REMOVE,REFIT ,REPLACE FRONT DISTANCE SENSORS.		70.00	50.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,700.00	1,080.00
	GRAND TOTAL		9,620.00	6,822.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,450.00
---	--	--	----------

Report Ref No. CC6/CTI22004234/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 2929C

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 2929C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMX 2929C

RE-INSPECTION

