

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2205-238

DATE : 6-May-2022

POLICY NO. : MSIG A300483055QMY

VEHICLE REG. NO. : SMX2929C

VEHICLE MAKE : Mercedes C180 AVANTGARDE (R17 LED)

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper A2058800340649999	1	\$ 1,800.00	\$ 1,800.00
2	Front Bumper Clip 003 990 9497	4	\$ 10.00	\$ 40.00
3	Front Bumper Lower Grille 205 885 0423	1	\$ 180.00	\$ 180.00
4	Front Bumper Side Retainer RH 205 885 0921	1	\$ 60.00	\$ 60.00
5	Front Bumper Side Grille RH 205 885 0823	1	\$ 120.00	\$ 120.00
6	Front Bumper Basic Carrier RH No. 20- 205 885 0665	1	\$ 100.00	\$ 100.00
7	Front Bumper Impact Absorber No. 40 205 885 0537	1	\$ 220.00	\$ 220.00
8	Front Bumper Upper Rubber Seal 205 628 1300	1	\$ 50.00	\$ 50.00
9	Head Lamp Unit RH - A2059067603	1	\$ 3,800.00	\$ 3,800.00
10	Front Reinforcement 205 620 2034	1	\$ 480.00	\$ 480.00
11	Front Reinforcement Bracket RH - A2056200495	1	\$ 250.00	\$ 250.00
12	Front Distance Sensor Wiring Harness A2055404007	1	\$ 200.00	\$ 200.00
13	Front Distance Sensor @ Bumper Inner RH A00090555049999	1	\$ 240.00	\$ 240.00
14	Front Distance Sensor @ Bumper Outer RH A00090556049999	1	\$ 240.00	\$ 240.00
15	Front Distance Sensor Decoupling Ring 000 542 1251	2	\$ 10.00	\$ 20.00
Total Spare Parts				\$ 7,800.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
16	Spray Paint Front Bumper, Fender RH and Bonnet	1	\$ 800.00	\$ 800.00
17	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 800.00	\$ 800.00
18	Remove, Refit, Replace Front Distance Sensors	1	\$ 70.00	\$ 70.00
19	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,700.00
Amount Before Excess				\$ 9,500.00
Add GST @ 7%				665.00
Total Amount Payable				\$ 10,165.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.