

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004246/ATY3N2**Date:** 31/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00024332203

**Claimant Vehicle No :** SKZ731G **Insured Vehicle No :** SLW2078A

Date of Loss: 11/04/2022 Nature of Claim: TP Claim No: SNM22D202466/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKZ731G**

Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4028539

Reg. Date: 07/01/2016 (Man. Year: 2015) Chassis No: RU11108536

Colour: White Odometer: 76475 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,036.56	2,154.48	2,882.08	57.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,030.00	1,750.00	62.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,816.56</b>	<b>3,184.48</b>	<b>4,632.08</b>	<b>59.26</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,550.00</b>		
<b>(\$\$)</b>	7,816.56	2,550.00	5,266.56	67.38
<b>+ GST 7.00/7.00% (\$\$)</b>	547.16	178.50	368.66	67.38
<b>Nett Amount (\$\$)</b>	<b>8,363.72</b>	<b>2,728.50</b>	<b>5,635.22</b>	<b>67.38</b>

**INSPECTION**

Date of Assignment: 06/05/2022

Date Inspected: 10/05/2022 Inspected At: Success United Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub  
Singapore 417921

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ731G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Not Necessary	655.00 FL	*- FL
2	10		*REAR BUMPER CLIPS	Not Necessary	45.00 FL	*- FL
3	1		*REAR BUMPER SIDE HOLDER LH	Not Necessary	37.50 FL	*- FL
4	1		*REAR FENDER LH	Repair	931.80 FL	*- FL
5	1		*REAR FENDER GUARD LH	Cut	250.00 FL	*250.00 FL
6	1		*SIDE ROCKER SKIRT LH	Not Necessary	350.00 FL	*- FL
7	1		*REAR DOOR LH	Dented	930.60 FL	*930.60 FL
8	1		*REAR DOOR MECHANISM LOCK LH	Not Necessary	195.80 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	86.50 FL	*- FL
10	1		*FRT DOOR LH	Dented	950.00 FL	*950.00 FL
11	1		*FRT DOOR WEATHERSTRIP LH	Not Necessary	153.80 FL	*- FL
12	1		*FRT FENDER LH	Not Necessary	521.70 FL	*- FL
13	1		*FRT FENDER GUARD LH	Not Necessary	250.00 FL	*- FL
14	1		*REAR SPORT RIM LH	Cut	750.40 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,108.10	2,580.60
- List Item Discount on L Items 20.00/20.00% (S\$)	1,071.54	426.12
Total Parts (S\$)	5,036.56	2,154.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTING	New	80.00	30.00
2	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,500.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,780.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >