



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0347/2022/JT
DATE : 28-Apr-22
WIP : 21770

Hui Rong,
06 days
\$11013.36.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-10 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS SNG SOK CHENG ANGELYN
ADDRESS : 22 CASSIA DRIVE
SINGAPORE 289715
TELEPHONE : HP +65 96839922
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100463055-06
VEHICLE NO : SCZ 2233 J
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 23/4/2015
ENGINE NO : CZC 233612
CHASSIS NO : WAUZZZ8VF1097137
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-22
PLACE OF ACCIDENT : CUSCADEN ROAD IN THE DIRECTION
OF TANGLIN ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL 6736 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCZ 2233 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	560
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY. ABCD PILLAR TRIMS. SILL TRIMS. FLOOR CARPETS. ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND AIRBAG.	S/N \$ 1,800.00	X
4	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. TO CUT OUT AND WELD LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,000.00	1500
5	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLES, HINGES, LHS SILL PANEL, LHS B-PILLAR AND DOOR ENTRANCE.	\$ 6,000.00	2950. 5 x 550 = 2750 Door handle x 4 = 200 2950
6	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 15,252.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCZ 2233 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	B-PILLAR - LH <i>Regis</i>	1	\$	3,078.00	*
2	WELD SCREW <i>He nee</i>	7	\$	14.00	*X
3	FRONT DOOR SILL TRIM STRIP - LH <i>nee</i>	1	\$	140.00	✓ 112
4	REAR DOOR SILL TRIM STRIP - LH <i>nee</i>	1	\$	77.00	X
5	PICTOGRAM STICKER <i>He nee</i>	1	\$	27.00	*X
6	FRONT DOOR - LH <i>Distorted</i>	1	\$	3,265.00	✓ 2612
7	FRONT DOOR BUNGS - LH <i>nee</i>	1	\$	5.00	X
8	FRONT DOOR OUTER SEAL - LH <i>nee</i>	1	\$	179.00	✓ 142.8
9	BONDING AGENT	1	\$	51.00	X
10	CLEANING SOLUTION	1	\$	74.00	X
11	APPLICATOR	1	\$	8.00	X
12	FRONT DOOR ATTACHMENT PARTS <i>nee</i>	1	\$	252.00	X
13	FRONT DOOR CATCH - LH <i>Damaged</i>	1	\$	72.00	✓ 75.20
14	FRONT DOOR HANDLE - LH <i>Regis</i>	1	\$	398.00	X
15	FRONT DOOR HOUSING <i>nee</i>	1	\$	58.00	X
16	REAR DOOR - LH <i>Distorted</i>	1	\$	3,265.00	✓ 2612
17	REAR DOOR BUNGS - LH <i>nee</i>	1	\$	5.00	X
18	REAR DOOR OUTER SEAL - LH <i>nee</i>	1	\$	179.00	✓ 142.80
19	BONDING AGENT	1	\$	51.00	X
20	CLEANING SOLUTION	1	\$	74.00	X
SUB TOTAL SPARE PARTS		:	\$	11,272.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCZ 2233 J

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	APPLICATOR <i>Not m</i>	1	\$	8.00	X
22	REAR DOOR ATTACHMENT PART <i>Not m</i>	1	\$	134.00	X
23	REAR DOOR CATCH - LH <i>Damaged</i>	1	\$	105.00	✓ 75.20
24	REAR DOOR HINGE UPPER / LOWER - LH <i>Not m</i>	2		TBC	X
25	REAR DOOR SEAL INNER - LH <i>Not m</i>	1	\$	213.00	X
26	REAR DOOR GUIDE SECTION - LH <i>Not m</i>	1	\$	75.00	X
27	ALUMINIUM RIM <i>Not m</i>	1	\$	1,303.00	X
28	RUBBER VALVE <i>Not m</i>	1	\$	4.00	X
29	ARYLIC SEALANT <i>Not m</i>	S/N	\$	180.00	X
30	CAVITY WAX <i>Not m</i>	S/N	\$	140.00	X
31	STONE CHIP <i>Not m</i>	S/N	\$	180.00	X
32	METAL FILLER POWDER <i>Not m</i>	S/N	\$	280.00	X
33	MUNDRIES <i>Not m</i>		\$	400.00	✓ 39.36
TOTAL SPARE PARTS		:	\$	14,294.00	
TOTAL LABOUR CHARGES		:	\$	15,252.00	
GRAND TOTAL		:	\$	29,546.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.