

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0347/2022/JT
DATE : 28-Apr-22
WIP : 21770

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS SNG SOK CHENG ANGELYN
ADDRESS : 22 CASSIA DRIVE
SINGAPORE 289715
TELEPHONE : HP +65 96839922
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100463055-06
VEHICLE NO : **SCZ 2233 J**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 23/4/2015
ENGINE NO : CZC 233612
CHASSIS NO : WAUZZZ8VF1097137
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Apr-22
PLACE OF ACCIDENT : CUSCADEN ROAD IN THE DIRECTION
OF TANGLIN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCZ 2233 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	X
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	360.
3	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND AIRBAG.	S/N \$	1,800.00	?
4	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. TO CUT OUT AND WELD LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,000.00	1500.
5	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLES, HINGES, LHS SILL PANEL, LHS B-PILLAR AND DOOR ENTRANCE.	\$	6,000.00	2950. 5 x 550 = 2750 Door handle x 2 = 200 <u>2950</u>
6	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	X.
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 15,252.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCZ 2233 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	B-PILLAR - LH <i>Repair</i>	1	\$ 3,078.00	<i>x</i>
2	WELD SCREW <i>?</i>	7	\$ 14.00	<i>?</i>
3	FRONT DOOR SILL TRIM STRIP - LH <i>new</i>	1	\$ 140.00	<i>✓</i>
4	REAR DOOR SILL TRIM STRIP - LH <i>new</i>	1	\$ 77.00	<i>x</i>
5	PICTOGRAM STICKER <i>?</i>	1	\$ 27.00	<i>?</i>
6	FRONT DOOR - LH <i>Distorted</i>	1	\$ 3,265.00	<i>✓</i>
7	FRONT DOOR BUNGS - LH <i>new new</i>	1	\$ 5.00	<i>x</i>
8	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 179.00	<i>✓</i>
9	BONDING AGENT <i>?</i>	1	\$ 51.00	<i>?</i>
10	CLEANING SOLUTION <i>?</i>	1	\$ 74.00	<i>?</i>
11	APPLICATOR <i>?</i>	1	\$ 8.00	<i>?</i>
12	FRONT DOOR ATTACHMENT PARTS <i>new new</i>	1	\$ 252.00	<i>x</i>
13	FRONT DOOR CATCH - LH <i>?</i>	1	\$ 72.00	<i>?</i>
14	FRONT DOOR HANDLE - LH <i>Repair</i>	1	\$ 398.00	<i>x</i>
15	FRONT DOOR HOUSING <i>new new</i>	1	\$ 58.00	<i>x</i>
16	REAR DOOR - LH <i>Distorted</i>	1	\$ 3,265.00	<i>✓</i>
17	REAR DOOR BUNGS - LH <i>new new</i>	1	\$ 5.00	<i>x</i>
18	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 179.00	<i>✓</i>
19	BONDING AGENT <i>?</i>	1	\$ 51.00	<i>?</i>
20	CLEANING SOLUTION <i>?</i>	1	\$ 74.00	<i>?</i>
SUB TOTAL SPARE PARTS		:	\$ 11,272.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCZ 2233 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	APPLICATOR ?	1	\$ 8.00	?
22	REAR DOOR ATTACHMENT PART Not m	1	\$ 134.00	+
23	REAR DOOR CATCH - LH ?	1	\$ 105.00	?
24	REAR DOOR HINGE UPPER / LOWER - LH not m	2	TBC	+
25	REAR DOOR SEAL INNER - LH not m	1	\$ 213.00	+
26	REAR DOOR GUIDE SECTION - LH not m	1	\$ 75.00	+
27	ALUMINIUM RIM Not m	1	\$ 1,303.00	+
28	RUBBER VALVE not m	1	\$ 4.00	+
29	ARYLIC SEALANT ?	S/N	\$ 180.00	+
30	CAVITY WAX { Not m	S/N	\$ 140.00	+
31	STONE CHIP	S/N	\$ 180.00	+
32	METAL FILLER POWDER Not m	S/N	\$ 280.00	+
33	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 14,294.00	
TOTAL LABOUR CHARGES		:	\$ 15,252.00	
GRAND TOTAL		:	\$ 29,546.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *05/05/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: