

NGS AUTOMOTIVE

Bik 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0062

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD
#09-01
SINGAPORE 068897

TEL : 6297 8802

FAX :

Your Ref. :

Our Ref. :

C. C. :

Date : 07/05/2022

Page : 1 of 2

Not Authorised
Anthony B. G. P. M.
5 days
\$ 4586.08

Description	Qty	U/ Price	Amount
		S\$	S\$
Accident on 29/04/2022 @19:17hrs Involving SLH2663P & SLZ746C			
Along SLE (Woodlands) Before Madai Lake Flyover			
Replacement Parts: Puegeot 5008			
Tailgate	1	1,456.80	1,456.80 ✓
Rubber, Tailgate	1	148.60	148.60 X
Outer Garnish, Tailgate	1	267.50	267.50 X
Rear Bumper	1	976.50	976.50 ✓
Tow Cover, Rear Bumper	1	46.20	46.20 X
Rear Bumper Lamp RH	1	179.00	179.00 ✓
Parking Sensor	1 ✓	208.00	208.00 ✓
Lock, Inner Lock	1	147.00	147.00 X
Reinforcement, Rr Bumper	1	468.00	468.00 ✓
Rear bracket RH/LH	2	89.00	178.00 X
Side Retainer RH/LH	2	158.00	316.00 X
End Panel Outer	1	390.60	390.60 X
End Panel Inner	1	576.70	576.70 X
Garnish, End Panel	1	104.90	104.90 X
Emblem "5008"	1	51.40	51.40 ✓
Emblem "Blue FDI"	1	58.80	58.80 ✓
Exhaust	1	1,257.00	1,257.00 X
SubTotal			7,455.00
Less 10%			-745.50
No Plate C/W Casing	S. Nett	50.00	50.00
Sealant	S. Nett	60.00	60.00
Moulding, Rear windscreen			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4586
4012

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.:53405718K

QUOTATION

No. : AQT-0062

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

TEL : 6297 8802

FAX :

Your Ref. :

Our Ref. :

C. C. :

Date : 07/05/2022


Page : 2 of 2

Description	Qty	U/ Price S\$	Amount S\$
To Remove Rear damaged part with all necessary component/attachment. Straighten Chassis member.	1	1,400.00	600 1,400.00
Repair/Reshape dented body panel. Replace Damaged Part. Refit into position.			
Transfer door Mechanism	1	150.00	600 150.00
Remove/Replace Exhaust	1	180.00	600 180.00
Transfer rear windscreen glass	1	280.00	1200 280.00
Spray Painting	1	1,000.00	600 1,000.00

Other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total **9,829.50**

Yours faithfully,


EVELYN

