



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2663P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	END PANEL INNER	TO REPAIR SEE LABOUR	576.70	-
1	TAILGATE	BENT	1,456.80	1,456.80
1	RUBBER, TAILGATE	SERVICEABLE	148.60	-
1	OUTER GARNISH, TAILGATE	SERVICEABLE	267.50	-
1	REAR BUMPER	CRACKED	976.50	976.50
1	TOW COVER, REAR BUMPER	SERVICEABLE	46.20	-
1	REAR BUMPER LAMP RH	BROKEN	179.00	179.00
4	PARKING SENSOR @\$208.00	SHORTED (1 PC ONLY)	832.00	208.00
1	LOCK, INNER LOCK	TO REPAIR SEE LABOUR	147.00	-
1	REINFORCEMENT, RR BUMPER	BENT	468.00	468.00
2	REAR BRACKET RH/LH @\$89.00	TO REPAIR SEE LABOUR	178.00	-
2	SIDE RETAINER RH/LH @\$158.00	SERVICEABLE	316.00	-
1	END PANEL OUTER	TO REPAIR SEE LABOUR	390.60	-
1	GARNISH, END PANEL	SERVICEABLE	104.90	-
1	EMBLEM "5008"	NECESSARY	51.40	51.40
1	EMBLEM "BLUE FDI"	NECESSARY	58.80	58.80
1	EXHAUST	TO REPAIR SEE LABOUR	1,257.00	-
	LESS 10% DISCOUNT		-745.50	-339.85
			6,709.50	3,058.65
<b><u>SPECIAL NETT ITEMS</u></b>				
1	NO. PLATE C/W CASING (SN)	BENT	50.00	45.00
1	SEALANT (SN)	NECESSARY	60.00	40.00
			110.00	85.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE REAR DAMAGED PART WITH ALL NECESSARY COMPONENT / ATTACHMENT. STRAIGHTEN CHASSIS MEMBER.REPAIR / RESHAPE DENTED BODY PANEL.REPLACE DAMAGED PART. REFIT INTO POSITION.INCLUSIVE OF THE REPAIR OF END PANEL INNER, LOCK, INNER LOCK, REAR BRACKET RH/LH, END PANEL OUTER AND EXHAUST.		1,400.00	600.00
	TRANSFER DOOR MECHANISM.		150.00	60.00
	REMOVE / REPLACE EXHAUST.		180.00	60.00
	TRANSFER REAR WINDSCREEN GLASS.		280.00	120.00
	SPRAY PAINTING.		1,000.00	600.00
			3,010.00	1,440.00
<b>GRAND TOTAL</b>			<b>9,829.50</b>	<b>4,583.65</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,583.65</b>

Report Ref No. CS/AIS22004262/Kty3z2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.