

Not Authorised
 Recovery B4 panel
 2 days



ESTIMATE TO REPAIR

VEHICLE NO. : SDS 1238 C
 MAKE : TOYOTA
 MODEL : COROLLA ATIS 1.6 CVT
 YEAR : 2016
 CHASSIS NO : MR053REH104559272

SURVEYOR NAME : Kenneth
 DATE OF SURVEY : 20.05.2022
 TIME OF SURVEY :

DATE : 5-May-22
 DATE OF ACCIDENT : 2-May-22
 THIRD PARTY REF : SLT 206 B / SOMPO

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			<i>Bumper</i>	\$589.50 ✓
2 ps	rear bumper retainer		\$116.00	<i>Pu</i>	\$232.00 X
2 ps	rear bumper bracket		\$64.00	<i>br</i>	\$128.00 X
10 ps	rear bumper clip		\$3.50	<i>cl</i>	\$35.00 ✓
1 pc	rear bumper sensor				\$496.60 ?
					\$1,481.10
	less 25%				\$370.28
					\$1,110.83
	To putty and spray paint.				\$350.00 22d
	Labour charges.				\$450.00 20d
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer: Signature: Date:					
TG-ML/-	TOTAL				\$1,910.83

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721