



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22002182/Eqy3e2-1	
			Date: 26/05/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 4728C	Veh. Inspected	GBD 7525L
	Policy No.	Z21VC05007325	Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025523	Excess (\$)	0.00
	Assign From	KENNY LIM	Assign Date	09/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTFAT35Y50K204011	Colour	WHITE
	Odometer	116047 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	GOODYEAR	4 mm
	L/H Front Tyre	195 R15C	GOODYEAR	4 mm
	R/H Rear Tyre	195 R15C	GOODYEAR	4 mm
	L/H Rear Tyre	195 R15C	GOODYEAR	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/03/2022	Inspection Date	09/03/2022
	Survey held at	TIAN SIANG MOTOR 27-A JURONG PORT ROAD #01-19, JURONG INDUSTRIAL ESTATE SINGAPORE 619101		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	