

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

FEB21EA10555

Name : TRADEWIN LOGISTICS PTE LTD

TPALG.

Make/Model : MITSUBISHI FUSO

Vehicle No : YN 9773 J

Xiao Tony

Accident date : 05.05.2022

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Front bumper <i>Buckled</i>	1	\$ 1,021.90 ✓
2	Front bumper side <i>garnish</i> holder @ \$394.90 <i>RH int</i>	2	\$ 789.80 394.90
3	Front grille <i>crushed</i>	1	\$ 1,458.30 950
4	Front grille centre emblem <i>new</i>	1	\$ 85.80 ✓
5	Front grille clips (1 set) <i>new</i>	1	\$ 60.00 30
6	Front corner panel @ \$630.00 <i>crushed.</i>	2	\$ 1,260.00 959
7	Front headlamp @ \$558.80 <i>crushed.</i>	2	\$ 1,117.60 ✓
8	Front headlamp side garnish @ \$394.90 <i>crushed.</i>	2	\$ 789.80 190
9	Front headlamp lower rubber @ \$ <i>new</i>	2	\$ <i>x</i>
10	Front side lamp @ \$297.00 <i>crushed.</i>	2	\$ 594.00 ✓
11	Front LH side mirror top cover <i>new</i>	1	\$ 34.00 <i>x</i>
12	Front LH side mirror top garnish <i>new</i>	1	\$ 34.10 <i>x</i>
13	Front RH door <i>Dented.</i>	1	\$ 2,200.00 1910
14	Front RH door top hinge <i>new</i>	1	\$ 178.20 <i>x</i>
15	Front RH door lower hinge <i>new</i>	1	\$ 178.20 <i>x</i>
16	Front RH door stopper <i>new</i>	1	\$ 94.60 <i>x</i>
17	Front step panel <i>Delaminate</i>	1	\$ 750.00 415
18	Front RH arch panel garnish <i>new</i>	1	\$ <i>x</i>

766820

575115

PROCEEDINGS BY LICENSING OF ENVIRONMENTAL PROTECTION AGENCY

CONFIDENTIALITY NOTICE

YN 9773J.

Sliding Door LH. Distorted

~~2500(SN)~~ 2000(SN)

Sliding Door Lock LH. Not nec

~~200(SN)~~ X

Sliding Door Front Pillar LH

Distorted ~~1400(SN)~~ 950(SN)

Sliding Door Lower Frame LH.

Dented ~~1200(SN)~~ 800(SN)

Sliding Door Lower Step Panel LH

Best ~~400(SN)~~ 280(SN)

Sliding Door Lower Protection Beam LH

Best ~~800(SN)~~ 500(SN)

Sliding Door Lower Protection Beam Bracket LH x 02

Best ~~250x250(SN)~~ 200(SN)

Rear Storage Box Body Panel LH

Dented ~~2500(SN)~~ 2000(SN)

Rear Storage Box Body Panel Pillar LH.

Not nec ~~1000(SN)~~ X
400(SN)

U Bolts x 06.

Best (4 pieces) ~~150x6 = 900(SN)~~

Rear Storage Box Horizontal Wooden Beam x 06.

5 pieces dented ~~2500(SN)~~ 2500(SN)
~~800x6 = 4800(SN)~~

Advertisement Stickers.

~~1800(SN)~~

New

1200(SN).

10830(SN)

YN9773J.

Panel Beating

Spray Painting

Wiring.

To spray buff coat.

To transfer door fittings.

To varnish wooden beams.

To lift up new storage box

~~2000.~~ 800

~~2000~~ 1000

~~100~~ 30

~~150~~ 80

~~150.~~ 80.

~~400~~ 300

~~800.~~ 650.

2940.

Total: 19521.15

r/s: 15.6K.

12 Days.

15.6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: