

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

MS/As 7my

Not Authorized
Lee

9/5/22

L/34 1800/

3 days

VEHICLE No: SMV 3146Z

1PC	REAR BUMPER	20/De	660.15	\$850.50	✓
2PCS	REAR BUMPER SIDE RETAINERS @ \$35.00	Lee		\$70.00	✓
1PC	REAR BUMPER CENTRE COVER	11		\$68.00	X
1SET	REAR BUMPER CLIPS	11		\$50.00	✓
1PC	REAR END PANEL	11		\$655.00	X
1PC	REAR END PANEL TOP GARNISH	11		\$311.05	X
1PC	TAILGATE WEATHERSTRIP	11		\$205.00	X
2PCS	TAILLAMPS @ \$645.00	11		\$1,290.00	X
1PC	TAILGATE	11	152	\$1,122.00	X
1PC	TAILGATE REAR LOGO	11	55.00	\$60.00	✓
1PC	TAILGATE 'SUZUKI' EMBLEM	11	48.00	\$62.00	✓
1PC	TAILGATE 'SWIFT' EMBLEM	11	52.00	\$68.00	✓
				\$4,811.55	

S.NETT

1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1O	REAR WINDSCREEN INNER SEAL	11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	shared	\$280.00	200
1PC	REAR LICENCE PLATE	Self	\$50.00	40

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$120.00	X
TO DISMANTLE & REFIX TAILGATE MECHANISM	11 \$100.00	X
TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	11 \$80.00	X
TO RESET & DIAGNOSTIC SYSTEM	\$120.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	420
TO PUTTY & SPRAY PAINTING	\$1,200.00	600
TOTAL	\$7,911.55	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 935.15
15-2

P-794-87

S-N-240

L-1220

225487

203

1803