

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days Res.: Yes or No

Lum Sum:

20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

23/5/22 4/5 @ 3800 in hand Alan.

Ume Asher

not Authorized
Lee
10/5/22
2/s 3800/
4 days

SMJ3881Y Toyota Vios

No	Qty	Parts Description	Parts Price
1	1	Front right door panel <i>Bodys 10/5/22</i>	\$ 1,020.40
2	1	Front right door panel black sticker <i>Lee</i>	\$ 68.80
3	1	Front right door inner board <i>11</i>	\$ 378.70 X
4	1	Front right door outer handle <i>11</i>	\$ 108.40 X
5	1	Front right door outer moulding <i>11</i>	\$ 128.90 X
6	1	Front right door lock mechanism <i>11</i>	\$ 215.30 X
7	1	Front right door lock cylinder <i>11</i>	\$ 127.60 X
8	1	Front right door weatherstrip <i>11</i>	\$ 186.50 X
9	1	Front right door regulator with motor assy <i>11</i>	\$ 478.50 X
10	2	Front right door hinges <i>11</i>	\$ 126.60 X
11	1	Front right door checker linkage <i>11</i>	\$ 130.10 X
12	1	Rear bumper assy <i>CU7/70cm 522.10</i>	\$ 589.20
13	1	Rear bumper right bracket <i>11</i>	\$ 88.30 X
14	1	Rear bumper right side retainer <i>11</i>	\$ 88.60 X
15	1	Rear bumper right reflector <i>11</i>	\$ 106.30 X
16	1	Rear bumper reinforcement <i>11</i>	\$ 319.30 X
17	1	Rear bootlid assy <i>11</i>	\$ 1,078.40 X
18	1	Rear bootlid weatherstrip <i>11</i>	\$ 168.70 X
19	1	Rear bootlid lock <i>11</i>	\$ 166.90 X
20	2	Rear bootlid hinges <i>11</i>	\$ 203.50 X
21	1	Rear bootlid centre logo <i>11</i>	\$ 68.80 X
22	1	Rear bootlid inner trim board <i>11</i>	\$ 221.30 X
23	1	Rear right bootlid taillamp <i>11</i>	\$ 326.30 X
24	1	Rear right taillamp <i>11</i>	\$ 568.30 X
25	1	Rear right fender assy <i>R</i>	\$ 1,283.20 X
26	1	Rear right fender inner cowlng <i>11</i>	\$ 88.70 X
27	1	Rear right fender inner garnish <i>11</i>	\$ 189.30 X
28	1	Rear right door panel <i>PS/30uf</i>	\$ 912.70
29	1	Rear right door panel black sticker <i>Lee</i>	\$ 68.80
30	1	Rear right door inner board <i>11</i>	\$ 378.70 X
31	1	Rear right door outer handle <i>11</i>	\$ 108.40 X
32	1	Rear right door outer moulding <i>11</i>	\$ 128.90 X
33	1	Rear right door lock mechanism <i>11</i>	\$ 215.30 X
34	1	Rear right door weatherstrip <i>11</i>	\$ 186.50 X
35	1	Rear right door regulator with motor assy <i>11</i>	\$ 478.50 X
36	2	Rear right door hinges <i>11</i>	\$ 126.60 X
37	1	Rear right door checker linkage <i>11</i>	\$ 130.10 X
38	1	Rear windscreen glass moulding <i>11</i>	\$ 188.80 X
39	1	Right side sill panel <i>DD 715.10</i>	\$ 1,890.30
40	1	Rear axle beam <i>11</i>	\$ 1,870.30 X
41	1	Rear right shock absorber assy <i>11</i>	\$ 492.20 X
42	1	Rear right wheel hub bearing <i>11</i>	\$ 251.20 X
			\$ 15,952.20
less 25%			\$ 3,988.05
			\$ 11,964.15

SMJ3881Y Toyota Vios

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	12 1 set	Rear bumper clips	ney \$ 60.00 50
2	1	Rear right wheel rim	wheel \$ 650.00 350
3	1	Rear right tyre	11 \$ 300.00 X
4	1	Rear no plate with garnish	11 \$ 100.00 X
5	8	Front right door inner board clips	11 \$ 50.00 X
6	8	Rear right door inner board clips	11 \$ 50.00 X
7	1	Rear right fender sealant	11 \$ 100.00 X
8	4	Rear right fender inner cowling clips	11 \$ 40.00 X
9	1 set	Rear right fender inner garnish clips	11 \$ 40.00 X
10	1	Rear windscreen glass sealant	11 \$ 100.00 X
11	2	Rear bumper reverse sensor	11 \$ 300.00 X
12	8	Rear bootlid inner trim board clips	11 \$ 50.00 X
			\$ 1,840.00
Total parts			\$ 13,804.15

SMJ3881Y Toyota Vios

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 1,000.00	700
2	To putty and spray painting front right portion.	\$ 1,000.00	900
3	To apply anti rust proofing to front right affected area.	\$ 140.00	60
4	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,400.00	X
5	To putty and spray painting rear right portion.	\$ 1,400.00	X
6	To check rear lighting and wiring.	\$ 50.00	20
7	To apply anti rust proofing to rear right affected area.	\$ 140.00	80
8	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	X
9	To remove and install rear bumper reverse sensor.	\$ 80.00	40
10	To remove and install rear right undercarriage parts.	\$ 350.00	X
11	To balance rear right wheel.	\$ 50.00	X
12	To conduct wheel alignment.	\$ 120.00	60
13	To remove and install front right door lock mechanism.	\$ 80.00	50
14	To remove and install rear right door lock mechanism.	\$ 80.00	50
15	To check front right and rear right door central locking for function.	\$ 80.00	X
16	To transfer front right door glass to new door.	\$ 80.00	X
17	To transfer rear right door glass to new door.	\$ 80.00	X
18	To remove and install front right door regulator with motor assy.	\$ 80.00	X
19	To remove and install rear right door regulator with motor assy.	\$ 80.00	X
20	Towing service.	\$ 100.00	X
Total labour :		\$ 6,530.00	

Total parts : \$ 13,804.15

Total labour : \$ 6,530.00

Total repair cost : \$ 20,334.15

P-3302-75
252
1-2477-06

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SN- 400
1- 1960
4837-06
202
3869.