



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: CYNTHIA ANG

Ref: CS/INC22004282/Eqy3e2

Date: 08/07/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 4092Y	Veh. Inspected	SBS 6547B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1170417-002	Excess (\$)	0.00
Assign From	Hazalysa Binte Ibrahim	Assign Date	09/05/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WEB62808323126619	Colour	MULTI COLOUR
Odometer	498154 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	DUNLOP	5 mm
L/H Front Tyre	295/80 R22.5	DUNLOP	5 mm
R/H Rear Tyre	295/80 R22.5 (D)	DUNLOP	5/5 mm
L/H Rear Tyre	295/80 R22.5 (D)	DUNLOP	5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/04/2022	Inspect Date / Time	09/05/2022 (08:11 PM)
Survey held at	11 TUAS BAY CLOSE #04-01/02 WEST STARS S636996		
Repairer	LEXBUILD INTERNATIONAL PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------