



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22004285/Eqy3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 21/10/2022

ATTN: QUEK SWEE KENG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMQ 6038J	Veh. Inspected	SHD 2376L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1171232-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	09/05/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GP72003537	Colour	BROWN
Odometer	102862 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	4 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	4 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	4 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/05/2022	Inspect Date / Time	09/05/2022 (11:00 AM)
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days