



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1170
Vehicle No.	: GBE5109M
Make & Model	: NISSAN NV200

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear fender outer panel LH <i>buc</i>		1637.00	
1	Tail lamp outer panel LH <i>? bt</i>		466.00	
1	Rear fender center track garnish LH <i>Xn</i>		168.00	X
1	Rear floor panel <i>rep buc</i>		1375.00	
1	End panel top garnish <i>? ca</i>		96.00	
1	Rear fender inner panel LH <i>bt</i>		1354.00	
1	Rear fender inner pillar panel LH <i>bt</i>		155.00	
1	Rear wheel housing outer panel LH <i>? repair</i>		373.00	X R
1	Tail lamp LH <i>buc</i>		252.00	
1	Rear bumper <i>de</i>		486.00	
2	Rear bumper side bracket LH/RH @2*\$38 <i>m</i>		76.00	
1	Rear bumper side reflector LH <i>m13</i>		62.00	
1	End panel inner <i>bt</i>		576.00	
1	End panel outer <i>bt</i>		157.00	
1	Rear trunk weatherstrip <i>m</i>		102.00	
1	Rear door RH weatherstrip <i>m</i>		70.00	
1	Rear door LH <i>bt</i>		1215.00	
1	Rear door inner trim board LH <i>de</i>		73.00	
1	Rear door upper lock LH <i>? Xn</i>		109.00	X
1	Rear door lower lock LH <i>? bt</i>		116.00	
1	Rear door central lock LH <i>? bt</i>		254.00	
1	Rear door upper hinge LH <i>? Xn</i>		108.00	X
1	Rear door lower hinge LH <i>? bt</i>		108.00	
1	Rear door checker LH <i>? Xn</i>		84.00	X
1	Rear door checker bracket LH <i>bt</i>		34.00	
1	Rear door logo badge <i>m</i>		65.00	
1	Rear door emblem "nv200" <i>m</i>		95.00	
1	Rear door emblem "dci" <i>m</i>		136.00	
1	Rear door center garnish LH <i>rep m</i>		352.00	
2	Rear car plate side lamp LH/RH @2*\$81 <i>ca/m4</i>		162.00	
1	Rear door outer handle <i>rep Xn</i>		254.00	X
1	Rear Wiper arm motor <i>? bt</i>		238.00	
1	Rear Wiper arm <i>Xn</i>		84.00	X
1	Rear Wiper arm cover <i>m13</i>		21.00	

1	Rear door RH	bt ✓	911.00	
1	Rear door upper lock RH	? XAN	109.00	X
1	Rear door lower lock RH	? bt ✓	116.00	
1	Front bumper	da. de ✓	542.00	
2	Front bumper side retainer LH/RH @2*\$27	XAN	54.00	X
1	Front bumper towing cover	de ✓	25.00	
1	Headlamp side lower garnish LH/RH @2*\$369	1 pc sn ✓	738.00	369
1	Front reinforcement	? st ✓	767.00	
1	Front bumper sponge	? cn ✓	272.00	
	TAILAMP panel inner cover - cn ✓		168.00	
		12903		
		30%		
		9032.10		
SPECIAL NETT ITEMS				
1	Rear bumper clips	m ✓	25.00	✓
1	Rear floor panel sealant	XAN	60.00	X
1	End panel sealant	m ✓	60.00	40
1	Rear fender sealant LH	m ✓	60.00	40
1	Rear door windscreen sealant LH	m ✓	60.00	80
1	Rear door windscreen sealant RH	m ✓	60.00	80
1	Rear fender sealant	m ✓	50.00	40
1	Rear Reverse Sensor	m ✓	200.00	m ✓
1	Front car plate with holder	bt ✓	35.00	✓
1	Rear car plate with holder	sea ✓	35.00	✓
1	Rear floor panel top board	cn ✓	300.00	200
1	Rear fender company sticker	m ✓	400.00	200
1	Rear both door company sticker	m ✓	400.00	200
1	70 km/h sticker	m ✓	20.00	10
1	Bizsafe 3 sticker	m ✓	80.00	50
Part Items Total:			14447.00	
			-10%	
			13002.30	
SN Items Total:			1845.00	
Total Parts:			14847.30	

1155



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH1170
Vehicle No. : GBE5109M
Make & Model : NISSAN NV200

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2008.00	1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1608.00	1000
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	90.00	60
4	To remove and replace Rear reverse sensor	100.00	60
5	To perform anti-rust treatment on affected areas	90.00	40
6	To remove and refit rear door LH windscreen	120.00	60
7	To remove and refit rear door RH windscreen	120.00	60
8	To remove and refit/replace rear compartment fitting, trimming, garnish, rear spare tyre with bracket and ect	100.00	60
Labour Total :		4220.00	
TOTAL (PARTS & LABOUR):		19067.30	

9032.10
1155.00
2840.00

13027.10

20%

10,421.68

H/S - \$10,400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pls
Hy 900 100 68

12 days
L/S

10/05/22 @ 1200

Reg after repair