



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2301027

INV Date 20/02/2023

Reference CS/EQI22004292/Bvy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SGW 378G
Insured Veh. SKJ 5090Z
Claim No. DM22HO00710/JT
Policy No. DMPPHQ21-00409
Accident Date 04/05/2022
Inspection Date 10/05/2022

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	300.00
GST (8%)	24.00
Grand Total	324.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Ref: CS/EQI22004292/Bvy3e2

Date: 20/02/2023

Code: EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 5090Z	Veh. Inspected	SGW 378G
Policy No.	DMPPHQ21-00409	Coverage (\$)	0.00
Claim No.	DM22HO00710/JT	Excess (\$)	0.00
Assign From	MELODY TEOH	Assign Date	09/05/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA HRV 1.5	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHRU1830GP000045	Colour	BLACK
Odometer	107532 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
L/H Front Tyre	225/50 R18	YOKOHAMA	6 mm
R/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm
L/H Rear Tyre	225/50 R18	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/05/2022	Inspection Date	10/05/2022
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 378G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED	1,436.20	1,436.20
1	TAILGATE LOGO	NECESSARY	95.80	95.80
2	TAILGATE LAMP @\$546.00	BROKEN	1,092.00	1,092.00
1	TAILGATE INNER LOCK	JAMMED	156.70	156.70
1	TAILGATE OUTER GARNISH	BROKEN	385.00	385.00
1	TAILGATE INNER TRIMBOARD	BROKEN	386.20	386.20
1	TAILGATE WEATHERSTRIP	TORN	198.40	198.40
1	TAILGATE INNER HANDLE	NOT DAMAGED	85.00	-
1	TAILGATE ANTENNA SENSOR	BROKEN	214.00	214.00
1	TAILGATE SMART BUZZER	BROKEN	195.00	195.00
1	REAR W/SCREEN MOULDING SIDE	NECESSARY	88.60	88.60
1	REAR W/SCREEN MOULDING TOP	NECESSARY	108.00	108.00
1	REAR WINDSCREEN MOULDING BOTTOM	NECESSARY	108.00	108.00
1	REAR BUMPER	BROKEN	989.50	989.50
2	REAR BUMPER SIDE RETAINER @\$85.00	NECESSARY	170.00	170.00
2	REAR BUMPER BRACKET @\$135.60	NO SUCH PARTS	271.20	-
2	REAR BUMPER REFLECTOR @\$128.00	BROKEN	256.00	256.00
2	REAR BUMPER SIDE GARNISH @\$238.90	BROKEN	477.80	477.80
1	REAR END PANEL	DENTED	695.80	695.80
1	REAR END PANEL TOP GARNISH	BROKEN	184.00	184.00
1	SPARE TYRE PANEL	DENTED	1,230.00	1,230.00
1	SPARE TYRE PANEL TOP BOARD	BROKEN	420.00	420.00
1	SPARE TYRE PANEL INSULATOR	NO SUCH PARTS	240.00	-
1	SPARE TYRE PANEL TOOLS TRAY	BROKEN	264.00	264.00
1	SPARE TYRE PANEL LOWER SPLASH COVER	NO SUCH PARTS	316.00	-
2	REAR FENDER @\$1425.80	NOT DAMAGED	2,851.60	-
2	REAR FENDER INNER TRIM BOARD @\$723.00	BROKEN	1,446.00	1,446.00
2	REAR FENDER ARCH GARNISH @\$218.30	BROKEN	436.60	436.60
2	TAILLAMP @\$658.30	BROKEN	1,316.60	1,316.60
1	EXHAUST PIPE	NOT DAMAGED	895.00	-
2	EXHAUST MOUNTING @\$42.50	TORN	85.00	85.00

Report Ref No. CS/EQI22004292/Bvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST HEAT SHIELD	NOT DAMAGED	185.00	-
1	BONNET	NOT DAMAGED	1,034.70	-
1	BONNET LOCK ASSY	NOT DAMAGED	234.60	-
1	FRONT BUMPER	BROKEN	1,050.00	1,050.00
1	FRONT BUMPER LOWER	NO SUCH PARTS	485.60	-
2	FRONT BUMPER SIDE RETAINER @\$72.00	NECESSARY	144.00	144.00
1	FRONT BUMPER REINFORCEMENT	BENT	486.00	486.00
1	FRONT BUMPER CENTRE GRILLE	BROKEN	198.60	198.60
2	FRONT BUMPER FOG LAMP @\$456.70	BROKEN	913.40	913.40
2	FRONT BUMPER FOG LAMP GARNISH @\$126.20	BROKEN	252.40	252.40
1	FRONT BUMPER TOW CAP	MISSING	83.20	83.20
2	FRONT GRILLE TOP BRACKET SIDE @\$87.30	NECESSARY	174.60	174.60
1	FRONT GRILLE TOP BRACKET CENTRE	NOT NECESSARY	198.00	-
2	HEADLAMP ASSY @\$2145.90	BROKEN	4,291.80	4,291.80
2	HEADLAMP BRACKET @\$76.00	NECESSARY	152.00	152.00
1	FRONT SUPPORT PANEL	NOT DAMAGED	898.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT DAMAGED	185.00	-
2	FRONT FENDER @\$785.00	NOT DAMAGED	1,570.00	-
2	FRONT FENDER ARCH PROTECTOR @\$128.90	NOT DAMAGED	257.80	-
1	AIRCON CONDENSER	DENTED	985.00	985.00
1	AIRCON SUCTION HOSE	NECESSARY	398.00	398.00
1	AIRCON DISCHARGE HOSE	NECESSARY	352.00	352.00
1	RADIATOR	NOT DAMAGED	987.90	-
	LESS 20% DISCOUNT		-6,522.32	-4,383.24
			26,089.28	17,532.96
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	TAILGATE SEALANT (SN)	NECESSARY	100.00	30.00
1	TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	50.00	20.00
2	TAILGATE LAMP CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
2	TAILGATE LAMP SEAL @\$60.00 (SN)	NECESSARY	120.00	20.00
1	TAILGATE INNER TRIMBOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE WINDSCREEN CLIPS (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/EQI22004292/Bvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE WINDSCREEN PRIMER AND CLEANER (SN)	NOT NECESSARY	80.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	60.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
2	REAR BUMPER SIDE GARNISH CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE PANEL LOWER SPLASH COVER CLIPS (SN)	NOT NECESSARY	50.00	-
2	REAR FENDER SEALANT @\$100.00 (SN)	NOT NECESSARY	200.00	-
2	REAR FENDER INNER TRIM BOARD CLIPS @\$50.00 (SN)	NECESSARY	100.00	40.00
2	REAR FENDER ARCH GARNISH CLIPS @\$50.00 (SN)	NECESSARY	100.00	30.00
1	REAR CHASSIS MEMBER SEALANT (SN)	NOT NECESSARY	100.00	-
2	TAILLAMP CLIPS @\$50.00 (SN)	NECESSARY	100.00	20.00
2	TAILLAMP SEAL @\$60.00 (SN)	NECESSARY	120.00	40.00
1	REAR NUMBER PLATE W/CASING (SN)	NOT NECESSARY	80.00	-
1	REVERSE CAMERA (SN)	NOT DAMAGED	480.00	-
2	REAR BUMPER REVERSE SENSOR @\$250.00 (SN)	SHORT CIRCUIT	500.00	200.00
1	BONNET SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER LOWER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER CENTRE GRILLE CLIPS (SN)	NECESSARY	50.00	20.00
2	FRONT BUMPER FOG LAMP GARNISH CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
1	FRONT GRILLE (CARBON FIBRE) (SN)	BROKEN	850.00	850.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT SUPPORT PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	20.00
2	FRONT FENDER SEALANT @\$100.00 (SN)	NOT NECESSARY	200.00	-
2	FRONT FENDER ARCH GARNISH CLIPS @\$50.00 (SN)	NECESSARY	100.00	20.00
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
1	AIR CON FLUID (SN)	NECESSARY	80.00	80.00
1	FRONT NUMBER PLATE W/CASING (SN)	BROKEN	80.00	60.00

Report Ref No. CS/EQI22004292/Bvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			5,010.00	1,770.00
	<u>LABOUR</u>			
	R&R TAILGATE COMPONENT.		150.00	80.00
	R&R TAILGATE WINDSCREEN.		250.00	120.00
	R&R REAR BUMPER REVERSE SENSOR.		100.00	60.00
	R&R REVERSE CAMERA.	NOT NECESSARY	150.00	-
	R&R EXHAUST PIPE.		150.00	50.00
	REAR CHECK WIRING.	NOT NECESSARY	100.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	100.00	-
	REAR UPHOLSTERY.	NOT NECESSARY	300.00	-
	REAR PANEL BEATING.		1,800.00	1,000.00
	REAR RUST PROOFING.	NOT NECESSARY	200.00	-
	REAR SPRAY PAINTING.		1,800.00	600.00
	R&R BONNET COMPONENT.	NOT NECESSARY	150.00	-
	R&R CONDENSER.		150.00	80.00
	R&R RADIATOR.		150.00	80.00
	FRONT CHECK WIRING.	NOT NECESSARY	100.00	-
	DIAGNOSTIC AND RESET FAULT CODE.	NOT NECESSARY	300.00	-
	FRONT UPHOLSTERY.	NOT NECESSARY	300.00	-
	FRONT PANEL BEATING.		1,200.00	600.00
	FRONT RUST PROOFING.	NOT NECESSARY	200.00	-
	FRONT SPRAY PAINTING.		1,200.00	400.00
			8,850.00	3,070.00
GRAND TOTAL			39,949.28	22,372.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/EQI22004292/Bvy3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/05/2022 11:50 (SGT)
Date of Accident 04/05/2022 20:15 (SGT)
Exact Location of Accident Bukit Batok Rd, Singapore
Additional Location Information TOWARDS TECK WHYE (BESIDE BLK 437A)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGW378G

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner THAM TUCK MENG CALVIN
NRIC No S8116312Z
Email Address calvinthamtuckmeng@gmail.com
Mobile Phone No (Phone) +65-91766079
Alternative Phone No +65-91766079

VEHICLE PARTICULARS

Manufacturer Honda
Model Hr-v
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1497

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 22-MR001776-R02
Cover Note Number -

DRIVER

Name of Driver THAM TUCK MENG CALVIN
NRIC No S8116312Z

Date Of Birth	02/06/1981
Occupation	Indoor
Date Of Driving Pass	11/12/2009
Driving experience	12 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91766079
Alt. Phone Number	+65-91766079
Email Address	calvinthamtuckmeng@gmail.com
Address	BLK 444 JURONG WEST AVENUE 1 #03-780
Address complement	-
Postcode	640444
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	TAN LI MING
Gender	Female

PASSENGER 2

Name	AMANDA WONG
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong Division Headquarters
Police Station Phone No	(Phone) +65-18007910000
Alt. Police Station Phone No	(Fax) +65-68965647
Police Station Address	No. 2 Jurong West Avenue 5 Singapore 649482
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT J/20220505/7028

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ5090Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC1596X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	THAM TUCK MENG CALVIN
Gender	Male
Phone No	(Phone) +65-91766079
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	SGW378G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	AMANDA WONG
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	SGW378G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 3

Name of injured person	TAN LI MING
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	SGW378G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

VECHA: SGW 3786
 VECHB: SKS 50902
 VECHC: SML 1596X

BULEN BAYOK RD TOWARDS TECK WHYE
 (BE SIDE BILK 43710)

WV WV
 W W

— — — — —

BUS STOP

Describe Circumstances of the Accident

AS STATED IN POLICE REPORT - J/20020505/9028

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



J/20220505/7028

1 of 2

POLICE REPORT (NP299)

Report No. J/20220505/7028

Police Station Of Origin
Jurong Division HQ
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7910000

Date/Time Report Made 05/05/2022 13:36	Vide Report No.	Station Diary No.
Name Of Informant THAM TUCK MENG CALVIN	Address 444 JURONG WEST AVENUE 1 #03-780 SINGAPORE 640444	
ID Type / ID No. NRIC NO / S8116312Z	Contact No. Home/Office:	Mobile: 91766079
Nationality SINGAPORE CITIZEN	Email Address CALVINTHAMTUCKMENG@GMAIL.COM	
Occupation Unemployed	Sex Male	Age 40
	Date of Birth 02/06/1981	Race Chinese
Institution/School Name	Language English	
Date/Time Of Incident 04/05/2022 20:15 - 04/05/2022 20:30	Location Of Incident BUKIT BATOK ROAD	

Brief details.

On the stated time and date, I (SGW378G) was driving along Bukit Batok road towards Teck Whye. While on the right most lane, the front vehicle slowed down to stop, and I followed suit. Suddenly, there was a huge impact from our rear and pushed my vehicle forward to collide onto the vehicle (SMC1596X) in front of my car. When we alighted to check, I realized that (SKJ5090Z) had failed to brake in time and collided onto our rear causing this chain collision. At the point of time, I have 2 passengers on in my car namely (Amanda Wong S9305729E) (Tan Li Ming G2338312N) I felt pain and discomfort and I went to Raffles medical to consult the doctor.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 05/05/2022 13:36
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



J/20220505/7028

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20220505/7028

Subjects Involved			
Victim			
Person Name	THAM TUCK MENG CALVIN		
ID Type	NRIC NO	ID No	S8116312Z
Gender	Male	Age	40
Race	Chinese	Language	English
Occupation	Unemployed	Address	444 JURONG WEST AVENUE 1 #03-780 SINGAPORE 640444
Mobile No	91766079	Is Informant A Victim?	Yes
Person Name	THAM TUCK MENG CALVIN (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:
The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
05/05/2022 13:36

Classification Of Case:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 378G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 378G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

