

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

**Insurer Reference: DM22H000710/JT**

**Repairer Reference:**

**Date calculated: 16/02/2023 4:39 PM**

**Full Report**

**Registration: SGW 378G**

**Printed: 17/02/2023 8:06 AM**

**Summary Information**

---

**Claim**

|                        |                |                   |                      |
|------------------------|----------------|-------------------|----------------------|
| Location:              | Singapore (SG) | Work Provider:    | EQ Insurance Pte Ltd |
| Printed by:            | KK LAU         | Currency:         | SGD                  |
| Claim Reference:       | DM22H000710/JT | Date of Incident: | 04/05/22             |
| Estimated Repair Time: |                | Hire Car Start:   |                      |
| Actual Repair Days:    |                | Hire Car End:     |                      |

**Vehicle Details**

---

**Vehicle**

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | HONDA             |
| Model:              | HR-V RU1/5        |
| Sub Model:          | LX                |
| Model Sheet Number: | 35 VE 09          |
| Registration:       | SGW 378G          |
| VIN number:         | MRHRU1830GP000045 |
| Odometer:           |                   |

**Model Specs**

|                   |                     |                     |                     |
|-------------------|---------------------|---------------------|---------------------|
| FROM MODEL 2018   | AUTO AIR CON        | FOG LAMPS           | SIDE FLASHER        |
| LED HEADLAMP      | REAR COMBI LIGHT    | RAIN-/DR/LIGHT SENS | CHROME DOOR HANDLES |
| REARVIEW CAMERA   | ULTRASONIC PARK SYS | 1.5 LTR 88KW        | WHEELS 7J X 16 ALY  |
| TWO COAT METALLIC | PREPARE OFF VEHICLE |                     |                     |

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



### Tyres Condition

| Tyre Brand | Tread (Left Middle),<br>mm | Tread (Left Outer),<br>mm | Tread (Left Inner),<br>mm | Tread (Right Inner),<br>mm | Tread (Right Outer),<br>mm | Tread (Right Middle),<br>mm | Condition |
|------------|----------------------------|---------------------------|---------------------------|----------------------------|----------------------------|-----------------------------|-----------|
|------------|----------------------------|---------------------------|---------------------------|----------------------------|----------------------------|-----------------------------|-----------|

| Spare Tyre Brand | Tread (Spare), mm |
|------------------|-------------------|
|------------------|-------------------|

### Labour

| Code       | Description                                                                                                    | Time Base 10 WU/h | Price = 60.00 SGD/h |           |
|------------|----------------------------------------------------------------------------------------------------------------|-------------------|---------------------|-----------|
|            |                                                                                                                |                   | WU                  | Price SGD |
| 8101A2 ZAX | RENEW FRONT BUMPER                                                                                             |                   | 17.0                | 102.00    |
| 813110)    | RENEW RADIATOR GRILLE                                                                                          |                   | 4.0                 | 24.00     |
| 8101B1)    | R + R FRONT BUMPER SUPPORT                                                                                     |                   | 2.0                 | 12.00     |
| 8101C1)    | R + R L/BUMPER CORNER SUPPORT                                                                                  |                   | 4.0                 | 24.00     |
| 8101C2)    | R + R R/BUMPER CORNER SUPPORT                                                                                  |                   | 4.0                 | 24.00     |
| 7121B7)    | R + R HEADLAMPS<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS                                              |                   | 8.0                 | 48.00     |
| 7141A0     | R + R LEFT OUTER TAILLAMP                                                                                      |                   | 1.0                 | 6.00      |
| 8131B7     | REMOVE AND REFIT L/R S-PANEL MOULDING                                                                          |                   | 2.0                 | 12.00     |
| 8131A8     | R + R LEFT REAR WHEELHOUSE SHELL                                                                               |                   | 3.0                 | 18.00     |
| 7141A5     | R + R RIGHT OUTER TAILLAMP                                                                                     |                   | 1.0                 | 6.00      |
| 8131B8     | REMOVE AND REFIT R/R S-PANEL MOULDING                                                                          |                   | 2.0                 | 12.00     |
| 8131A9     | R + R RIGHT REAR WHEELHOUSE SHELL                                                                              |                   | 3.0                 | 18.00     |
| 8111A5 ZAX | RENEW REAR BUMPER<br>INCLUDES: REMOVE AND REFIT REAR BUMPER,<br>BUMPER CORNERS AND REQUIRED ATTACHED<br>PARTS. |                   | 8.0                 | 48.00     |

| Code                             | Description                                                                                  | WU           | Price SGD       |
|----------------------------------|----------------------------------------------------------------------------------------------|--------------|-----------------|
| 8111A1 ZAX                       | R + R L/R OUTER PARKING AID SENSOR                                                           | 1.0          | 6.00            |
| 823100                           | RENEW TAILGATE<br>INCLUDES: R + R TAILGATE,<br>CONVERT ATTACHED PARTS, RENEW IF<br>NECESSARY | 32.0         | 192.00          |
| NO NUMBER                        | RENEW REAR PANEL                                                                             | 42.0         | 252.00          |
| 8571C8)                          | R + R L/R SIDE PANEL TRIM                                                                    | 2.0          | 12.00           |
| 8571C9)                          | R + R R/R SIDE PANEL TRIM                                                                    | 2.0          | 12.00           |
| NO NUMBER                        | CALIBRATE CAMERA                                                                             | 6.0          | 36.00           |
| 616100)                          | R + R CONDENSER                                                                              | 2.0          | 12.00           |
| 616156)                          | R + R CONDENSER-EVAPORATOR HOSE                                                              | 3.0          | 18.00           |
| 616185)                          | R + R CONDENSER-/COMPRESSOR HOSE                                                             | 5.0          | 30.00           |
| 620020                           | DRAIN + REFILL AIR CONDITIONING                                                              | 7.0          | 42.00           |
| 4211F3 ZAX                       | FIT + BALANCE TYRE (SPARE WHEEL)                                                             | 4.0          | 24.00           |
| 4211A6                           | R + R SPARE WHEEL/TYRE                                                                       | 2.0          | 12.00           |
| <b>Labour Cost</b>               |                                                                                              | <b>Hrs</b>   | <b>WU</b>       |
| <b>Panel / Mechanical Labour</b> |                                                                                              | <b>16.70</b> | <b>167.0</b>    |
| <b>Total of Labour</b>           |                                                                                              |              | <b>1,002.00</b> |

## Paint

| Paint Work |                                         | SYSTEM AZT | Time Basis 10 WU/h |
|------------|-----------------------------------------|------------|--------------------|
| Code       | Description - TWO COAT METALLIC         | WU         | Price SGD          |
|            | REAR PANEL NEW PART PAINTING            | 19.0       |                    |
|            | BOOTLID/TAILGATE NEW PART PAINTING      | 19.0       |                    |
|            | FRONT BUMPER NEW PART PAINT K1R         | 10.0       |                    |
|            | FRT TOWING EYE COVER NEW PART PAINT K1R | 3.0        |                    |
|            | REAR BUMPER NEW PART PAINT K1R          | 10.0       |                    |
|            | L/R BUMPER CORNER NEW PART PAINT K1R    | 4.0        |                    |
|            | R/R BUMPER CORNER NEW PART PAINT K1R    | 4.0        |                    |
|            | TAILGATE TRIM NEW PART PAINT K1R        | 4.0        |                    |
|            | L/R OUT PARKING SENS NEW PART PAINT K1R | 3.0        |                    |

## Paint Material Per Part

| Code | Description                             | Price SGD |
|------|-----------------------------------------|-----------|
| 2711 | REAR PANEL NEW PART PAINTING            | 20.90     |
| 2931 | BOOTLID/TAILGATE NEW PART PAINTING      | 59.86     |
| 0283 | FRONT BUMPER NEW PART PAINT K1R         | 43.30     |
| 0300 | FRT TOWING EYE COVER NEW PART PAINT K1R | 0.49      |
| 2583 | REAR BUMPER NEW PART PAINT K1R          | 44.28     |
| 2587 | L/R BUMPER CORNER NEW PART PAINT K1R    | 10.33     |
| 2588 | R/R BUMPER CORNER NEW PART PAINT K1R    | 10.33     |
| 2593 | TAILGATE TRIM NEW PART PAINT K1R        | 10.33     |
| 2669 | L/R OUT PARKING SENS NEW PART PAINT K1R | 0.49      |

| <b>Labour Cost - Paint</b>     |                    | <b>Hrs</b>   | <b>WU</b>    | <b>Price SGD</b> |
|--------------------------------|--------------------|--------------|--------------|------------------|
| Factor                         | <b>60.00 SGD/h</b> |              |              |                  |
| Time Paint                     |                    |              | <b>76.0</b>  |                  |
| Preparation Main Work Metal    |                    | <b>2.50</b>  | <b>25.0</b>  | <b>150.00</b>    |
| Preparation Comp. Work Plastic |                    | <b>0.50</b>  | <b>5.0</b>   | <b>30.00</b>     |
| <b>Total</b>                   | <b>10 WU/h</b>     | <b>10.60</b> | <b>106.0</b> | <b>636.00</b>    |

| <b>Material Cost - Paint</b>        |  |  |  | <b>Price SGD</b> |
|-------------------------------------|--|--|--|------------------|
| New Part Painting                   |  |  |  | <b>80.76</b>     |
| New Part Painting - Plastic K1R     |  |  |  | <b>119.55</b>    |
| Material-constant Metal Preparation |  |  |  | <b>28.60</b>     |
| Material-constant Plastic           |  |  |  | <b>9.00</b>      |
| <b>Total</b>                        |  |  |  | <b>237.91</b>    |

## Spare Parts

|             |                      |                    |                    | <b>prices as at 2015-06-01/01</b> |  |
|-------------|----------------------|--------------------|--------------------|-----------------------------------|--|
| <b>Code</b> | <b>Description</b>   | <b>Part Number</b> | <b>Part Source</b> | <b>Price SGD</b>                  |  |
| 9986        | AIR CON COOLANT      | NO NUMBER          | Original           | <b>80.00</b>                      |  |
| 2977        | BOOT/TAILGATE LOCK   | 74800T7YK01        | Original           | <b>156.70</b>                     |  |
| 2944        | BOOT/TAILGATE SEAL   | 74440T7A003        | Original           | <b>198.40</b>                     |  |
| 4994        | BOOT FLOOR PANEL CVR | 84521T7AJ01ZA      | Original           | <b>420.00</b>                     |  |
| 4929        | BOOT FLOOR TRAY      | 84400T7AJ01ZA      | Original           | <b>264.00</b>                     |  |
| 2931        | BOOTLID/TAILGATE     | 68100T8NQ10ZZ      | Original           | <b>1,436.20</b>                   |  |
| 3170        | CHECK                | 91502S70003        |                    | <b>0.00</b>                       |  |
| 3171        | CHECK                | 91501S70003        |                    | <b>0.00</b>                       |  |
| 3173        | CHECK                | 91536SS0J01        |                    | <b>0.00</b>                       |  |
| 4481        | COND/COMPRESSOR      | 80315T7YF01        | Original           | <b>398.00</b>                     |  |
|             | HOSE                 |                    |                    |                                   |  |
| 4482        | COND/EVAPORATOR      | 80341T7YF01        | Original           | <b>352.00</b>                     |  |
|             | PIPE                 |                    |                    |                                   |  |
| 4465        | CONDENSER            | 80110T7YF01        | Original           | <b>985.00</b>                     |  |
| 9987        | COOLANT/ANTIFREEZE   | NO NUMBER          | Original           | <b>40.00</b>                      |  |
| 4985        | END PANEL TRIM       | 84640T7AJ01ZA      | Original           | <b>184.00</b>                     |  |
| 1001        | Exhaust Mounting     | EM                 | Original           | <b>85.00</b>                      |  |
| 0283        | FRONT BUMPER         | 04711T7AJ00ZZ      | Original           | <b>1,050.00</b>                   |  |
| 0340        | FRT BUMPER SUPPORT   | 71130T7AJ00ZZ      | Original           | <b>486.00</b>                     |  |
| 0260        | FRT NO PLATE REINF   | 71145S21000        | Original           | <b>60.00</b>                      |  |
| 0300        | FRT TOWING EYE COVER | 71104T7AJ00ZH      | Original           | <b>83.20</b>                      |  |
| 0410        | GRILLE               | 71121T7AG01        | Original           | <b>198.60</b>                     |  |
| 4907        | INNER TAILGATE TRIM  | 84431T7AJ01ZA      | Original           | <b>386.20</b>                     |  |
| 0343        | L/BUMPER CORNER      | 71190T7AJ00        | Original           | <b>72.00</b>                      |  |
|             | BRKT                 |                    |                    |                                   |  |
| 3679        | L/FASTENING CLIP     | 91505TM8003        | Original           | <b>40.00</b>                      |  |
| 3691        | L/FASTENING CLIP     | 90144SEA000        | Original           | <b>30.00</b>                      |  |
| 0637        | L/F FOG LAMP         | 71108T7AJ00        | Original           | <b>456.70</b>                     |  |
| 0561        | L/F HEADLAMP CPL     | 33150T7SE11        | Original           | <b>2,145.90</b>                   |  |
| 0649        | L/FOG LAMP COVER     | 71106T7AJ10        | Original           | <b>126.20</b>                     |  |
| 0319        | L/F UPP BUMPER BRKT  | 71198T7AJ00        | Original           | <b>87.30</b>                      |  |
| 0415        | L/RAD-GRILLE BRACKET | 71152T7AJ00        | Original           | <b>76.00</b>                      |  |
| 2587        | L/R BUMPER CORNER    | 04718T7AJ00ZZ      | Original           | <b>0.00</b>                       |  |
| 3283        | L/R INNER LAMP       | 34155T7AH11        | Original           | <b>546.00</b>                     |  |
| 2671        | L/R INN PARKING SENS | 39680TV0305ZZ      | Original           | <b>200.00</b>                     |  |
| 2619        | L/R OUT BUMPER BRKT  | 71598T7AJ00        | Original           | <b>85.00</b>                      |  |
| 3281        | L/R OUTER LAMP       | 33552T7AH11        | Original           | <b>658.30</b>                     |  |

| Code | Description           | Part Number        | Part Source | Price SGD |
|------|-----------------------|--------------------|-------------|-----------|
| 2669 | L/R OUT PARKING SENS  | 39680TV0E11ZN      | Original    | 214.00    |
| 3295 | L/R REFLECTOR         | 33555T7AJ01        | Original    | 128.00    |
| 3671 | L/R S-PANEL MOULDING  | 74450T7B003        | Original    | 218.30    |
| 3675 | L/R WHEELHOUSE COVER  | 74592T7A010        | Original    | 723.00    |
| 3167 | L/R WINDOW SEAL       | 73265T7A003        | Original    | 88.60     |
| 0353 | L/SCREW               | 90144TL0G00        | Original    | 30.00     |
| 0357 | L/SCREW               | 90144TL0G00        | Original    | 30.00     |
| 3161 | LWR REAR SCREEN SEAL  | 73226SZW000        | Original    | 108.00    |
| 0344 | R/BUMPER CORNER BRKT  | 71140T7AJ00        | Original    | 72.00     |
| 3678 | R/FASTENING CLIP      | 91505TM8003        | Original    | 40.00     |
| 3690 | R/FASTENING CLIP      | 90144SEA000        | Original    | 30.00     |
| 0638 | R/F FOG LAMP          | 71107T7AJ00        | Original    | 456.70    |
| 0562 | R/F HEADLAMP CPL      | 33100T7SE11        | Original    | 2,145.90  |
| 0650 | R/FOG LAMP COVER      | 71105T7AJ10        | Original    | 126.20    |
| 0320 | R/F UPP BUMPER BRKT   | 71193T7AJ00        | Original    | 87.30     |
| 0416 | R/RAD-GRILLE BRACKET  | 71151T7AJ00        | Original    | 76.00     |
| 2588 | R/R BUMPER CORNER     | 04717T7AJ00ZZ      | Original    | 238.90    |
| 3284 | R/R INNER LAMP        | 34150T7AH11        | Original    | 546.00    |
| 2620 | R/R OUT BUMPER BRKT   | 71593T7AJ00        | Original    | 85.00     |
| 3282 | R/R OUTER LAMP        | 33502T7AH11        | Original    | 658.30    |
| 3296 | R/R REFLECTOR         | 33505T7AJ01        | Original    | 128.00    |
| 3672 | R/R S-PANEL MOULDING  | 74410T7B003        | Original    | 218.30    |
| 3676 | R/R WHEELHOUSE CVR    | 74552T7A010        | Original    | 723.00    |
| 0354 | R/SCREW               | 90144TL0G00        | Original    | 30.00     |
| 2583 | REAR BUMPER           | 04715T7A900ZZ      | Original    | 989.50    |
| 2711 | REAR PANEL            | 66100T8NT00ZZ      | Original    | 695.80    |
| 3163 | REAR SCREEN FIX SET   | USE SINGLE PARTS   | Original    |           |
| 9696 | SPARE TYRE            | 135/90 R 16 .. M   | Original    | 1,230.00  |
| 1000 | Tailgate Smart Buzzer |                    | Original    | 195.00    |
| 2593 | TAILGATE TRIM         | 74890T7A013ZN      | Original    | 385.00    |
| 3165 | UPP R-SCREEN SEAL     | SEE GUIDE NO. 3161 | Original    | 108.00    |

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

|                                   |                  |
|-----------------------------------|------------------|
| <b>Savings</b>                    | <b>0.00</b>      |
| <b>Subtotal</b>                   | <b>22,191.50</b> |
| <b>Subtotal Discount(+20.00%)</b> | <b>-4,438.30</b> |
| <b>Total</b>                      | <b>17,753.20</b> |

## Extras

| Code | Description         | Price SGD     |
|------|---------------------|---------------|
| 1002 | All Clips, Sealant  | 440.00*       |
|      | <b>Total Extras</b> | <b>440.00</b> |

## Final Calculation

|                                       | SGD       | SGD              |
|---------------------------------------|-----------|------------------|
| <b>Parts</b>                          | 22,191.50 |                  |
| Total Discount(+20.00%)               | -4,438.30 |                  |
| <b>Total Parts</b>                    |           | <b>17,753.20</b> |
| <b>Labour Time Base 10 WU/h</b>       |           |                  |
| Total 167.0 WU X 60.00 SGD/h          | 1,002.00  |                  |
| <b>Total of Labour</b>                |           | <b>1,002.00</b>  |
| <b>Total Of Extras</b>                |           | <b>440.00</b>    |
| <b>Paint Work Time Base 10 WU/h</b>   |           |                  |
| Labour Cost 106.0 WU X 60.00 SGD/h    | 636.00    |                  |
| Material Cost                         | 237.91    |                  |
| <b>Total Paint Including Material</b> |           | <b>873.91</b>    |
| <b>Repair Cost Excludes GST</b>       |           | <b>20,069.11</b> |
| GST (+8.0%)                           |           | <b>1,605.53</b>  |
| <b>Repair Cost Included GST</b>       |           | <b>21,674.64</b> |

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.