

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004293/UQY3M4**Date:** 13/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00062682200
Claimant Vehicle No :	SLC4245B	Insured Vehicle No :	SJQ9934M
Date of Loss:	05/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203101/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4245B	Engine No:	1ZR562610
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104548949
Reg. Date:	13/05/2016 (Man. Year: 2016)	Odometer:	71570 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,962.40	5,463.47	12,498.93	69.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	2,420.00	720.00	22.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,102.40	7,883.47	13,218.93	62.64
Approved Total (Overridden) (S\$)		7,583.48		
(S\$)	21,102.40	7,583.48	13,518.92	64.06
+ GST 7.00/7.00% (S\$)	1,477.17	530.84	946.33	64.06
Nett Amount (S\$)	22,579.57	8,114.32	14,465.25	64.06

INSPECTION

Date of Assignment:	09/05/2022	
Date Inspected:	10/05/2022	Inspected At: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$5,674.88 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC4245B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	563.00 FL	*563.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
3	1		*FOG LAMP - LH	Not Necessary	329.00 FL	*- FL
4	1		*FOG LAMP GARNISH - LH	Not Necessary	128.80 FL	*- FL
5	1		*FRONT FENDER - LH	Badly Dented	965.30 FL	*965.30 FL
6	1		*FRONT FENDER COWLING - LH	Distorted	240.80 FL	*240.80 FL
7	10		*FRONT FENDER COWLING CLIPS - LH	Necessary	55.00 FL	*55.00 FL
8	1		*FRONT FENDER DUAL VVTI WORDINGS	Necessary	47.70 FL	*47.70 FL
9	1		*FRONT FENDER QUARTER GARNISH - LH	Not Necessary	46.90 FL	*- FL
10	1		*FRONT DOOR - LH	Dented / Bent	1,355.20 FL	*1,355.20 FL
11	1		*FRONT DOOR STICKER - LH	Necessary	50.90 FL	*50.90 FL
12	1		*FRONT DOOR RUBBER - LH	Necessary	191.00 FL	*191.00 FL
13	1		*FRONT DOOR OUTER CHANNEL MOULDING	Not Necessary	120.40 FL	*- FL
14	1		*REAR DOOR - LH	Dented / Bent	1,323.00 FL	*1,323.00 FL
15	1		*REAR DOOR STICKER - LH	Necessary	46.20 FL	*46.20 FL
16	1		*REAR DOOR RUBBER - LH	Necessary	191.00 FL	*191.00 FL
17	1		*REAR DOOR OUTER CHANNEL MOULDING - LH	Not Necessary	146.20 FL	*- FL
18	1		*ROCKER PANEL OUTER GARNISH - LH	Not Necessary	480.50 FL	*- FL
19	1		*SIDE MIRROR ASSY - LH	Not Necessary	1,335.50 FL	*- FL
20	1		*SIDE MIRROR OUTER COVER - LH	Not Necessary	116.00 FL	*- FL
21	1		*FRONT ABSORBER TOP MOUNTING	Not Necessary	232.20 FL	*- FL
22	1		*REAR WHEEL AXLE	Not Necessary	3,616.70 FL	*- FL
23	1		*REAR TYRE - LH	Serviceable	280.00 FS	*- FS
24	1		*FRONT TYRE - LH	Serviceable	280.00 FS	*- FS
25	1		*HEAD LAMP - LH	* Check	3,180.20 FL	*- FL
26	1		*FRONT DOOR TOP HINGE - LH	* Check	103.10 FL	*- FL
27	1		*FRONT DOOR LOWER HINGE - LH	* Check	103.10 FL	*- FL
28	1		*FRONT LOWER ARM - LH	* Check	776.40 FL	*- FL
29	1		*FRONT LOWER ARM BALL JOINT - LH	* Check	779.40 FL	*- FL
30	1		*FRONT ABSORBER - LH	* Check	464.70 FL	*- FL
31	1		*FRONT KNUCKLE - LH	* Check	666.90 FL	*- FL
32	1		*FRONT KNUCKLE BEARING - LH	* Check	77.00 FL	*- FL
33	1		*REAR KNUCKLE BEARING - LH	* Check	1,015.70 FL	*- FL
34	1		*FRONT RIM - LH	Cut	1,599.75 FS	*800.00 FS
35	1		*REAR RIM - LH	Cut	1,599.75 FS	*800.00 FS
36	1		*FRONT BUMPER SIDE HOLDER -LH/RH (2PCS)	N/s Bent	134.40 FL	*67.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,696.70	6,751.30
- List Item Discount on L Items 25.00/25.00% (S\$)	4,734.30	1,287.83
Total Parts (S\$)	17,962.40	5,463.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	New	800.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,400.00	1,200.00
3	TO CHECK WIRING	New	40.00	30.00
4	TO TRANSFER 2 DOOR & DOOR FITTINGS	New	180.00	120.00
5	TO TUFF-KOTE	New	120.00	90.00
6	TO 4 WHEEL ALIGNMENT	New	80.00	80.00
7	TO REMOVE, REPLACE FRONT LEFT UNDERCARRIAGE	New	300.00	300.00
8	TO REMOVE, REPLACE FRONT REAR UNDERCARRIAGE	New	150.00	0.00
9	TO REMOVE, REFIT 2RIM & BALANCE TYRES	New	70.00	0.00
Gross Labour Cost (\$)			3,140.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >