

23/5



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SNE1552A

Chassis No : JHMRV3800NS200068

Model : HRV DX-SIN CVT YM 2022

Owner's Name : CHENG HSIAO LING

Ins Policy No. :

Date of Accident : 6/5/2022

Document No. : SQT22001260

Date : 9. May 2022

Customer No. : WZC008

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L15ZK1100068

Date | Time : 9. May 2022 9:04:23 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHENG HSIAO LING OWNER INSURER: Tokio Marine ACC DATE: 06/05/2022 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: PC9130T						
68100-3M0-E00ZZ	TAILGATE COMP ✓ <i>DR</i>	1	916.70	25	687.52	48.13	735.65 ✓
91513-T6A-003	CLIPTAILGATE SPOILER ✓ <i>nc</i>	9	2.60	25	17.55	1.23	18.78 ✓
75722-3N0-E01	EMBLEM SET,RR. ✓ <i>nc</i>	1	35.70	25	26.77	1.87	28.64 ✓
34150-3M0-J02	LIGHT ASSY,R,LID ✓ <i>DR</i>	1	463.00	25	347.25	24.31	371.56 ✓
33500-3M0-J01	LIGHT ASSY,R,TAIL ✓ <i>X nn</i>	1	437.50	25	328.12	22.97	351.09 ✓
04715-3M0-000ZZ	FACE,RR.BUMPER ✓ <i>DR</i>	1	564.20	25	423.15	29.62	452.77 ✓
71560-3M0-G00	FACE ASSY RR BPR ✓ <i>CR4</i>	1	488.30	25	366.22	25.64	391.86 ✓
71630-3M0-003	SPACER,R,RR.BPR S ✓ <i>nc</i>	1	19.00	25	14.25	1.00	15.25 ✓
71680-3M0-003	SPACER,L,RR.BPR S ✓ <i>nc</i>	1	19.00	25	14.25	1.00	15.25 ✓
91505-TM8-003	CLIP,BUMPER ✓ <i>nc</i>	6	2.30	25	10.35	0.72	11.07 ✓
74410-3M0-J01	PROTECTOR, R,RR.W ✓ <i>X nn</i>	1	97.20	25	72.90	5.10	78.00 ✓
66100-3M0-300ZZ	PANEL COMP,REAR ✓ <i>X nn</i>	1	516.20	25	387.15	27.10	414.25 ✓
73213-3M0-000	RUBBER,R.WSHLD DA ✓ <i>nc</i>	1	12.70	25	9.52	0.67	10.19 ✓
73215-3M0-000	RUBBER,WSHLD DAM ✓ <i>nc</i>	1	26.60	25	19.95	1.40	21.35 ✓
73216-3M0-000	SPACER,RR.WINDSHIELD ✓ <i>nc</i>	2	2.90	25	4.35	0.30	4.65 ✓
73226-SZW-000	DAMPERSTD 5X5 ✓ <i>nc</i>	1	9.10	25	6.82	0.48	7.30 ✓
73263-3M0-000	RUBBER,L.WSHLD DA ✓ <i>nc</i>	1	12.70	25	9.52	0.67	10.19 ✓
91502-TTA-003	CLIP,RR.WINDSHIELD LOWER ✓ <i>nc</i>	2	4.30	25	6.45	0.45	6.90 ✓
91502-TXA-J01	CLIP,RR.WINDSHIELD UPPER ✓ <i>nc</i>	2	2.90	25	4.35	0.30	4.65 ✓

Printed on 9/5/2022 9:38:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Page 2

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SNE1552A
Chassis No : JHMRV3800NS200068
Model : HRV DX-SIN CVT YM 2022
Owner's Name : CHENG HSIAO LING
Ins Policy No. :
Date of Accident : 6/5/2022

Document No. : SQT22001260
Date : 9. May 2022
Customer No. : WZC008
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15ZK1100068
Date | Time : 9. May 2022 9:04:23 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
				Sum Item	2756.44	192.96	2,949.40
BOSUN	SUNDRIES	1	100.00	50 /	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	19.60	299.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	480	560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00	480	560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00	100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT TAILGATE	1	120.00	100	120.00	8.40	128.40
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3900.00	1300	3900.00	273.00	4173.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	3120.00	1560	3120.00	218.40	3338.40
				Sum Labor	10340.00	723.80	11,063.80

Survey By

Date & Time

Excess

Status

Signature

Total Amount 13,096.44 916.76 14,013.20

Total (Inclusive of GST) 14,013.20

10942.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 9/5/2022 9:38:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.