

ASS. REC. BY:

REF:

ASS. REC. BY:

REF:

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cob

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 045 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SITC 5678B Yr Regn: 08, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prow c.c. 1798Colour M.P. White / Red A/C: Insured / Std / NI / NASp. Reading 92813 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU503092462Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rlm / STD / Rlm or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 21/4/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1) GIA not ready

Date/Time, File Pass to?

☐ : Prel. Report1) _____
Date/Time, File Return to?☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS. \$ _____

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: Site Insp (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B*Not Attached
Recovery B4 part***AAD2205-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 MAY 2022**SHC5678B**

JTDKB3FU503092462

200303878K

TOYOTA

PRIUS GEN 4

21/04/2022

YN2741L/FCI

31/08/2021

PART**LIST**

1	COVER, REAR BUMPER	\$	<i>Bu</i>	485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$		332.70	7
1	COVER, REAR BUMPER, LOWER	\$	<i>Lu</i>	22.00	X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Lu</i>	374.50	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>Lu</i>	132.60	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Lu</i>	132.60	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>Lu</i>	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>Lu</i>	139.80	X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	\$	<i>Lu</i>	54.40	X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$	<i>Lu</i>	54.40	X
1	MOULDING SUB-ASSY, ROOF TOP	\$	<i>CM</i>	656.90	✓
1	BLADE, RR WIPER	\$	<i>Lu</i>	56.90	X
1	ARM, REAR WIPER	\$	<i>Lu</i>	102.40	X
1	GARNISH, BACK DOOR SIDE, LH	\$	<i>Lu</i>	95.60	X
1	GARNISH, BACK DOOR SIDE, RH	\$	<i>Lu</i>	95.60	X
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	<i>Bu</i>	339.60	✓
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	<i>Bu</i>	261.00	✓
1	LENS & BODY, REAR COMBINATION LAMP, LH (Upper)	\$	<i>Lu</i>	339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH (Lower)	\$	<i>Lu</i>	261.00	X
1	LAMP ASSY, REAR, LH	\$	<i>Lu</i>	293.60	X
1	LAMP ASSY, REAR, RH	\$	<i>Bu</i>	293.60	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>Lu</i>	1,147.80	✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>Lu</i>	54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>Lu</i>	54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>Lu</i>	47.90	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>Bu</i>	913.60	✓
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>CM</i>	259.20	✓

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH
- 1 SEAL, REAR SPOILER
- 1 SPOILER SUB-ASSY, REAR
- 1 LAMP ASSY, CENTER STOP
- 1 GLASS, BACK WINDOW FIX
- 1 MOULDING, BACK WINDOW, LOWER NO.2
- 1 MOULDING, BACK WINDOW, OUTSIDE LH NO.2
- 1 MOULDING, BACK WINDOW, OUTSIDE RH NO.2
- 1 DAM, BACK DOOR GLASS ADHESIVE, NO.2
- 1 GLASS, BACK DOOR
- 1 BOARD, REAR FLOOR, NO.1
- 1 WEATHERSTRIP, BACK DOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

\$	Pn	52.10	X
\$	R	467.00	X
\$	Mr	16.70	—
\$	CM	1,575.40	—
\$	BN	192.30	—
\$	Shorewall	761.40	—
\$	Mr	23.60	—
\$	Mr	30.90	—
\$	Mr	30.90	—
\$	Mr	28.90	—
\$	Shorewall	1,656.70	—
\$	Sn	519.00	X
\$	Sn	372.30	X
\$	Pn	126.70	X
\$		651.00	?
\$	Sn	242.50	X
\$	Sn	242.50	X
\$	DT	61.00	—
\$	DT	61.00	—

TOTAL \$ 14,985.50**25% \$ 3,746.38****\$ 11,239.13****Special Nett**

- 1SET PARKING AID
- 1 REAR SPOILER CLIP
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP
- 1 REAR NUMBER PLATE WITH MOULDING

\$	Sn	700.00	X
\$	Mr	70.00	—
\$	Mr	95.00	60SN
\$	Mr	150.00	80SN
\$	Mr	200.00	—
\$	Mr	130.00	30SN
\$	Mr	80.00	30SN
\$	Mr	80.00	30SN
\$	NJP	180.00	X
\$	Mr	85.00	X
\$	Mr	65.00	X
\$	BT	200.00	45SN

TOTAL \$ 2,035.00

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

TOTAL PARTS \$ 13,274.13**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	1801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	7001 11001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	11001
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *na* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *na* 220.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *na* 380.00 X**TOTAL** \$ **8,390.00****Over All Total** \$ **21,664.13****(PART-BY-PART) Repair Days**~~25 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**