

ASS. REC. BY:

REF:

F02/ 22004300/KV

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

045 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SITC 5678B

Yr Regn:

08, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pro

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

92813

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31F-U503092462

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Sailun

Front

Rear

R/Bal.

R/Bal.

mm

mm

L/Bal.

L/Bal.

mm

mm

D.O.A.

21/4/22

D.O.I.

9/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA not ready

30/5, 89960.30 Cash

Date/Time, File Pass to?

☐

Prell. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + R.S. SI

Fees

Others

TOTAL

1)

Date/Time, File Return to?

☐

Final Report

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHC5678B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H09910
Chassis No.:	JTDKB3FU503092462
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	31 Aug 2021
First Registration Date:	31 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$7,030.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2029
PARF Rebate Amount:	\$5,272.00

Intended COE Rebate Details

COE Expiry Date:	30 Aug 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,087.00
COE Rebate Amount:	\$29,669.00
Total Rebate Amount:	\$34,941.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 May 2022

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B*Not Notified
Penny B4 pay***AAD2205-***89960.30*

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 MAY 2022**SHC5678B**

JTDKB3FU503092462

200303878K

TOYOTA

PRIUS GEN 4

21/04/2022

YN2741L/FCI

31/08/2021

PART**LIST**

1	COVER, REAR BUMPER	\$	<i>Bu</i>	485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>As</i>	332.70	✓
1	COVER, REAR BUMPER, LOWER	\$	<i>Sm</i>	22.00	X
1	GUARD, REAR BUMPER, CENTER	\$	<i>As</i>	374.50	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>Sm</i>	132.60	X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sm</i>	132.60	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>R</i>	871.50	X
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>Sm</i>	139.80	X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	\$	<i>Sm</i>	54.40	X
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$	<i>Sm</i>	54.40	X
1	MOULDING SUB-ASSY, ROOF TOP	\$	<i>CM</i>	656.90	✓
1	BLADE, RR WIPER	\$	<i>Sm</i>	56.90	X
1	ARM, REAR WIPER	\$	<i>Sm</i>	102.40	X
1	GARNISH, BACK DOOR SIDE, LH	\$	<i>Sm</i>	95.60	X
1	GARNISH, BACK DOOR SIDE, RH	\$	<i>Sm</i>	95.60	X
1	LENS & BODY, REAR COMBINATION LAMP, RH (Upper)	\$	<i>Bu</i>	339.60	✓
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (Lower)	\$	<i>Bu</i>	261.00	✓
1	LENS & BODY, REAR COMBINATION LAMP, LH (Upper)	\$	<i>Sm</i>	339.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH (Lower)	\$	<i>Sm</i>	261.00	X
1	LAMP ASSY, REAR, LH	\$	<i>Sm</i>	293.60	X
1	LAMP ASSY, REAR, RH	\$	<i>Bu</i>	293.60	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>As</i>	1,147.80	✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>As</i>	54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>As</i>	54.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>As</i>	47.90	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>Bu</i>	913.60	✓
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>CM</i>	259.20	✓

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH
- 1 SEAL, REAR SPOILER
- 1 SPOILER SUB-ASSY, REAR
- 1 LAMP ASSY, CENTER STOP
- 1 GLASS, BACK WINDOW FIX
- 1 MOULDING, BACK WINDOW, LOWER NO.2
- 1 MOULDING, BACK WINDOW, OUTSIDE LH NO.2
- 1 MOULDING, BACK WINDOW, OUTSIDE RH NO.2
- 1 DAM, BACK DOOR GLASS ADHESIVE, NO.2
- 1 GLASS, BACK DOOR
- 1 BOARD, REAR FLOOR, NO.1
- 1 WEATHERSTRIP, BACK DOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

\$	Pu	52.10	X
\$	R	467.00	X
\$	M	16.70	—
\$	CM	1,575.40	—
\$	BR	192.30	—
\$	Shorewall	761.40	—
\$	M	23.60	—
\$	M	30.90	—
\$	M	30.90	—
\$	M	28.90	—
\$	Shorewall	1,656.70	—
\$	Sn	519.00	X
\$	Sn	372.30	X
\$	Pu	126.70	X
\$	R	651.00	X
\$	Sn	242.50	X
\$	Sn	242.50	X
\$	Di	61.00	—
\$	Di	61.00	—
TOTAL	\$	14,985.50	
25%	\$	3,746.38	
	\$	11,239.13	

Special Nett

- 1SET PARKING AID
- 1 REAR SPOILER CLIP
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP
- 1 REAR NUMBER PLATE WITH MOULDING

\$	Sn	700.00	X
\$	M	70.00	—
\$	M	95.00	60SN
\$	M	150.00	80SN
\$	M	200.00	—
\$	M	130.00	30SN
\$	M	80.00	30SN
\$	M	80.00	30SN
\$	NIP	180.00	X
\$	N	85.00	X
\$	N	65.00	X
\$	BT	200.00	45SN
TOTAL	\$	2,035.00	

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

TOTAL PARTS	\$	13,274.13
--------------------	-----------	------------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	1801
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	701 11001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	11001
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *na* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *na* 220.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *na* 380.00 X**TOTAL** \$ **8,390.00****Over All Total** \$ **21,664.13****(PART-BY-PART) Repair Days****25 DAYS***5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: