

(08/11/13) , wef

ASS. REC. BY: Marcus

REF:

CS/ GA122004309/Uqy3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 22/5/22

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.F. (\$

TOTAL

24/5/22 2/5 9700 insured Alien cred to 10970.50, 532)

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

submit to ins.

Not Authorized
rule

9/5/22

2/5 & 9700/
6 day.

VEHICLE No: SLT 4735P

1PC	REAR WINDSCREEN	shattered	1250.00	\$1,488.00	
1PC	REAR WINDSCREEN MOULDING	nee		\$110.20	
1PC	TAILGATE	Badly D	1288.30	\$1,699.20	
1PC	TAILGATE 'H' LOGO	nee	35.00	\$45.00	
1PC	TAILGATE 'FREED' EMBLEM	nee		\$95.00	
1PC	TAILGATE 'HYBRID' EMBLEM	nee		\$105.00	
1PC	TAILGATE OUTER HANDLE GARNISH	one	365.20	\$450.00	
2PCS	TAILGATE REFLECTORS @\$486.20	one	420.50 x 2 = 841	\$972.40	
1PC	TAILGATE INNER LOCK	twi	166.00	\$199.80	
1PC	TAILGATE LOCK STRIKER	11		\$66.00	X
1PC	TAILGATE INNER TRIM BOARD	De/one		\$435.00	
1SET	TAILGATE INNER TRIM BOARD CLIPS	nee		\$50.00	
1PC	TAILGATE WEATHERSTRIP	twi		\$288.00	
1PC	TAILGATE REAR WIPER MOTOR	Sent/Jan	605	\$645.00	
1PC	TAILGATE REAR WIPER ARM	11		\$288.00	X
1PC	REAR BUMPER	D/D/Torn	845.30	\$1,280.00	
1PC	REAR BUMPER TOW COVER	De		\$20.00	
2PCS	REAR BUMPER REFLECTORS @\$151.00	11		\$302.00	X
1SET	REAR BUMPER CLIPS	nee	40.00	\$50.00	
1PC	REAR END PANEL OUTER	badly D	576.90	\$665.20	
1PC	REAR END PANEL INNER	badly D		\$445.10	
1PC	REAR END PANEL TOP GARNISH	twi	281.20	\$341.10	
2PCS	TAILLAMPS @\$650.00	one		\$1,300.00	
2PCS	TAILLAMP HOUSING PANELS @\$350.00	N/SR	old sent 325	\$700.00	1PC
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.00	N/SR	old sent	\$790.00	1PC
1PC	REAR FLOOR PANEL	R		\$1,120.00	X
1PC	REAR FLOOR PANEL TOP CARPET	waged/Torn	611.20	\$620.50	
2PCS	REAR LICENCE PLATE LAMPS @\$45.00	11		\$90.00	X
				\$14,660.50	

(202)

S.NETT

1SET	REAR VIDEO CAM ASSY	m.s	\$480.00	350
1PC	REAR LICENCE PLATE	Sent	\$50.00	40
1PC	REAR WINDSCREEN SEALANT	nee	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	nee	\$50.00	40
1PC	REAR END PANEL SEALANT	nee	\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	shorted	\$280.00	200
1SET	REAR REVERSE CAMERA	shorted	\$450.00	300
1SET	REAR FLOOR PANEL INSULATOR	nee	\$300.00	200

TO CEHCK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFX REAR WINDSCREEN	\$150.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO DISMANTLE & REFIX FUEL TANK	11 \$120.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$180.00	50
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO SPRAY RUST PROOFING	\$100.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	1000
TO PUTTY & SPRAY PAINTING	\$1,500.00	1100
TOTAL	\$20,670.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-10473-40
202
P-8378-72
S.N-1220
L-2570
1216872
202
9734