

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 03/05/2022
TP Veh Reg No: SMM1721Z

Estimate No: EST2200144
Date: 06 May 2022

Veh Reg No: SMD8805S
Make/Model: AUDI A3 SEDAN 1.4
TFSI COD S TRONIC
Chasis No: WAUZZZ8V0J1078160
Reg. Date: 10/09/2018
Your Ref No: SMM1721Z

Estimate Repair Cost to Vehicle No :SMD8805S

| <u>Quantity</u> | <u>Description</u> | <u>List Price</u> | <u>Amount</u> |
|-----------------|---------------------------------|-------------------|---------------|
| | | <u>S\$</u> | <u>S\$</u> |
| | List Price | | |
| 1 | 1 PC BOOT LID | 3,657.00 | |
| 2 | 2 PCS BOOTLID HINGE | 570.00 | |
| 3 | 1 PC BOOTLID EMBLEM | 143.50 | |
| 4 | 1 PC BOOTLID "A3" EMBLEM | 103.50 | |
| 5 | 1 PC BOOT LID "TFSI" EMBLEM | 103.50 | |
| 6 | 1 PC BOOT LID LAMP RH | 973.50 | |
| 7 | 1 PC BOOT LID LAMP LH | 973.50 | |
| 8 | 2 PCS REAR NUMBER PLATE LAMP | 209.00 | |
| 9 | 1 PC REVERSE CAMERA | 1,478.00 | |
| 10 | 1 PC BOOT LID RUBBER | 288.50 | |
| 11 | 1 PC BOOT LID LOCK | 270.50 | |
| 12 | 1 PC BOOT LID LOCK CHECKER | 66.40 | |
| 13 | 1 PC BOOT LID TRIM | 385.00 | |
| 14 | 2 PCS BOOT LID TRIM SIDE RUBBER | 323.40 | |
| 15 | 1 PC BOOT LID KEYLESS SENSOR | 178.40 | |
| 16 | 1 PC REAR PANEL | 772.50 | |
| 17 | 1 PC REAR PANEL TRIM | 171.50 | |
| 18 | 1 PC REAR SPARE TYRE HARDBOARD | 780.10 | |
| 19 | 1 PC REAR LH FENDER TRIM | 841.00 | |
| 20 | 1 PC REAR FENDER TRIM RH | 841.00 | |
| 21 | 1 PC TAIL LAMP LH | 973.50 | |
| 22 | 1 PC TAIL LAMP PANEL LH | 299.40 | |
| 23 | 1 PC TAIL LAMP - RH | 973.50 | |
| 24 | 1 PC TAIL LAMP PANEL RH | 299.40 | |
| 25 | 1 PC REAR BUMPER | 1,944.00 | |
| 26 | 1 PC REAR BUMPER REINFORCEMENT | 641.50 | |
| 27 | 1 PC REAR BUMPER TOP BEAM | 303.90 | |
| 28 | 2 PCS REAR BUMPER SIDE RETAINER | 148.40 | |
| 29 | 4 PCS REVERSE SENSORS | 975.60 | |

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
 190 CLEMENCEAU AVE #03-01
 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
 ATTN: Motor Claim Department

Estimate No: EST2200144
Date: 06 May 2022

Veh Reg No: SMD8805S
Make/Model: AUDI A3 SEDAN 1.4
 TFSI COD S TRONIC
Chasis No: WAUZZZ8V0J1078160

Claim Type: Third Party
Accident Date: 03/05/2022
TP Veh Reg No: SMM1721Z

Reg. Date: 10/09/2018
Your Ref No: SMM1721Z

Estimate Repair Cost to Vehicle No :SMD8805S

| Quantity | Description | List Price | Amount |
|--------------------|---|------------|------------|
| | | <u>S\$</u> | <u>S\$</u> |
| 30 | 1 PC REAR BUMPER REFLECTOR - RH | 45.60 | |
| 31 | 1 PC REAR BUMPER REFLECTOR - LH | 45.60 | |
| 32 | 1 PC REAR LOWER SPOILER | 483.50 | |
| 33 | 1 PC REAR TOWING COVER | 48.90 | |
| 34 | 2 PCS REAR BUMPER BRACKET | 139.80 | |
| 35 | 1 PC EXHAUST PIPE | 775.50 | |
| | | 21,227.90 | |
| | | Less 10% | 19,105.11 |
| | | 2,122.79 | |
| Special Net | | | |
| 36 | 1 PC REAR NUMBER PLATE | 50.00 | |
| 37 | 1 SET BOOTLID TRIM CLIPS | 60.00 | |
| 38 | 1 SET REAR PANEL TRIM CLIPS | 40.00 | |
| 39 | 1 SET REAR FENDER TRIM CLIPS LH | 60.00 | |
| 40 | 1 SET REAR FENDER TRIM CLIPS RH | 60.00 | |
| 41 | 1 SET REAR LOWER SPOILER CLIPS | 40.00 | |
| 42 | 1 SET REAR BUMPER CLIPS | 60.00 | |
| | | 370.00 | 370.00 |
| Labour | | | |
| 43 | 1 TO CHECK WIRING | 80.00 | |
| 44 | 1 TO REMOVE AND REFIT REVERSE CAMERA | 80.00 | |
| 45 | 1 TO REMOVE AND REFIT REVERSE SENSOR | 80.00 | |
| 46 | 1 TO REMOVE AND REFIX REAR EXHAUST PIPE | 150.00 | |
| 47 | 1 TO REMOVE AND REFIT INNER TRIM | 200.00 | |
| 48 | 1 TO SPRAY PANEL SEALANT | 180.00 | |
| 49 | 1 (REAR) TO SPRAY PAINTING | 1,500.00 | |
| 50 | 1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS. | 1,600.00 | |
| | | 3,870.00 | 3,870.00 |

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 03/05/2022
TP Veh Reg No: SMM1721Z

Estimate No: EST2200144

Date: 06 May 2022

Veh Reg No: **SMD8805S**

Make/Model: AUDI A3 SEDAN 1.4
TFSI COD S TRONIC

Chasis No: WAUZZZ8V0J1078160

Reg. Date: 10/09/2018

Your Ref No: SMM1721Z

Estimate Repair Cost to Vehicle No :SMD8805S

| Quantity | Description | List Price | Amount |
|----------|-------------|----------------------|----------------------|
| | | S\$ | S\$ |
| | | Total | S\$ 23,345.11 |
| | | Add GST @ 7% | 1,634.16 |
| | | Total Amount Payable | <u>S\$ 24,979.27</u> |

TOTAL: SINGAPORE DOLLAR TWENTY FOUR THOUSAND NINE HUNDRED SEVENTY NINE AND CENTS TWENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE