



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Ref: CS/AGI22004310/Aqy3q2

Date: 17/01/2023

Code: AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMM 1721Z	<b>Veh. Inspected</b>	SMD 8805S
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10015095/JM	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SHAFAWATI MD RABU	<b>Assign Date</b>	09/05/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	AUDI A3	<b>c.c</b>	1395
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	WAUZZZ8VOJ1078160	<b>Colour</b>	BLACK
<b>Odometer</b>	35201 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/55 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	205/55 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	205/55 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	205/55 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/05/2022	<b>Inspection Date</b>	09/05/2022
<b>Survey held at</b>	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**