



# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 5, #02-06 Aunbury @ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST 201300201N

M/S: AUTO & GENERAL INSURANCE (S) PTE LTD  
 190 CLEMENCEAU AVE #03-01  
 SINGAPORE SHOPPING CENTRE  
 SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853  
 ATTN: Motor Claim Department

Estimate No: EST2200144  
 Date: 06 May 2022

Veh Reg No: SMD8805S  
 Make Model: AUDI A3 SEDAN 1.4 TFSI COD S TRONIC  
 Chasis No: WAUZZZ8V0J1078160  
 Reg. Date: 10/09 2018  
 Your Ref No: SMMI721Z

Claim Type: Third Party  
 Accident Date: 03/05/2022  
 TP Veh Reg No: SMMI721Z

*Xiao Chen*

### Estimate Repair Cost to Vehicle No :SMD8805S

Quantity	Description	List Price	Amount
		SS	SS
1	1 PC BOOT LID <i>Dented</i>	3,657.00	-
2	2 PCS BOOTLID HINGE <i>new Best</i>	570.00	-
3	1 PC BOOTLID EMBLEM	143.50	-
4	1 PC BOOTLID "A3" EMBLEM <i>2 new</i>	103.50	-
5	1 PC BOOT LID "TFSI" EMBLEM	103.50	-
6	1 PC BOOT LID LAMP RH <i>at</i>	973.50	-
7	1 PC BOOT LID LAMP LH <i>new cracked</i>	973.50	+ ✓ <i>sls</i>
8	2 PCS REAR NUMBER PLATE LAMP <i>new new</i>	209.00	+ X
9	1 PC REVERSE CAMERA	1,478.00	+ ✓
10	1 PC BOOT LID RUBBER <i>at</i>	288.50	-
11	1 PC BOOT LID LOCK <i>Dented</i>	270.50	-
12	1 PC BOOT LID LOCK CHECKER <i>new Best</i>	66.40	+ ✓ <i>sls</i>
13	1 PC BOOT LID TRIM <i>Dented</i>	385.00	-
14	2 PCS BOOT LID TRIM SIDE RUBBER <i>LH missing</i>	<del>323.40</del> 161.70	-
15	1 PC BOOT LID KEYLESS SENSOR <i>cracked</i>	178.40	? ✓ <i>sls</i>
16	1 PC REAR PANEL <i>Distorted</i>	772.50	-
17	1 PC REAR PANEL TRIM <i>Dented</i>	171.50	-
18	1 PC REAR SPARE TYRE HARDBOARD <i>Dented</i>	780.10	? ✓ <i>sls</i>
19	1 PC REAR LH FENDER TRIM <i>cracked</i>	841.00	? ✓ <i>sls</i>
20	1 PC REAR FENDER TRIM RH <i>new</i>	841.00	+ ✓ <i>sls</i>
21	1 PC TAIL LAMP LH <i>cracked</i>	973.50	-
22	1 PC TAIL LAMP PANEL LH <i>Repair</i>	299.40	+ X
23	1 PC TAIL LAMP - RH <i>cracked</i>	973.50	? ✓ <i>sls</i>
24	1 PC TAIL LAMP PANEL RH <i>Repair</i>	299.40	+ X
25	1 PC REAR BUMPER <i>Distorted</i>	1,944.00	-
26	1 PC REAR BUMPER REINFORCEMENT <i>Distorted</i>	641.50	✓
27	1 PC REAR BUMPER TOP BEAM <i>new</i>	303.90	? ✓ <i>sls</i>
28	2 PCS REAR BUMPER SIDE RETAINER <i>cracked</i>	148.40	? ✓ <i>sls</i>
29	4 PCS REVERSE SENSORS <i>2 pieces missing</i>	<del>973.50</del> 487.50	✓

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave n, #02-06 Autobay @ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST 201300201N

M/S: AUTO & GENERAL INSURANCE (S) PTE LTD  
 190 CLEMENCEAU AVE #03-01  
 SINGAPORE SHOPPING CENTRE  
 SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853  
 ATTN: Motor Claim Department

Estimate No: EST2200144  
 Date: 06 May 2022

Veh Reg No: SMD8805S  
 Make/Model: AUDI A3 SEDAN 1.4 TFSI COD S TRONIC  
 Chasis No: WAUZZZ8V0J1078160  
 Reg. Date: 10/09/2018  
 Your Ref No: SMM1721Z

Claim Type: Third Party  
 Accident Date: 03/05/2022  
 TP Veh Reg No: SMM1721Z

## Estimate Repair Cost to Vehicle No :SMD8805S

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	45.60	+
31	1 PC REAR BUMPER REFLECTOR - LH <i>rehd</i>	45.60	7 ✓ <i>88.5</i>
32	1 PC REAR LOWER SPOILER <i>Delhd</i>	483.50	✓
33	1 PC REAR TOWING COVER <i>new</i>	48.90	x
34	2 PCS REAR BUMPER BRACKET <i>rehd</i>	139.80	2 ✓ <i>88.5</i>
35	1 PC EXHAUST PIPE <i>new</i>	775.50	+
	<i>1 pc spare type top sponge</i>	21,227.90	
	<i>1 pc side returner bracket</i>	2,122.79	
	<i>Special Net</i>		
36	1 PC REAR NUMBER PLATE <i>Best</i>	50.00	✓
37	1 SET BOOTLID TRIM CLIPS <i>re</i>	60.00	30
38	1 SET REAR PANEL TRIM CLIPS <i>re</i>	40.00	20
39	1 SET REAR FENDER TRIM CLIPS LH <i>new</i>	60.00	30
40	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	60.00	30
41	1 SET REAR LOWER SPOILER CLIPS <i>new</i>	40.00	20
42	1 SET REAR BUMPER CLIPS <i>re</i>	60.00	50
		370.00	370.00
	<b>Labour</b>		
43	1 TO CHECK WIRING	80.00	30
44	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
45	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	60
46	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00	+
47	1 TO REMOVE AND REFIT INNER TRIM	200.00	80
48	1 TO SPRAY PANEL SEALANT	180.00	60
49	1 (REAR) TO SPRAY PAINTING	1,500.00	1400
50	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING WELDING WORKS.	1,600.00	1400
	<i>To perform diagnostic test.</i>	200.150	3,870.00
	<i>To transfer bootlid fittings</i>	250.80	3,870.00

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6 #02-06 AutoBay@Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD  
 190 CLEMENCEAU AVE #03-01  
 SINGAPORE SHOPPING CENTRE  
 SINGAPORE 239924  
 TEL: 6221 2199 FAX: 6725 0853  
 ATTN: Motor Claim Department

Estimate No: EST2200144  
 Date: 06 May 2022  
 Veh Reg No: SMD8805S  
 Make/Model: AUDI A3 SEDAN 1.4  
 TFSI COD S TRONIC  
 Chasis No: WAUZZZ8V0J1078160  
 Reg. Date: 10/09/2018  
 Your Ref No: SMMI721Z

Claim Type: Third Party  
 Accident Date: 03/05/2022  
 TP Veh Reg No: SMMI721Z


## Estimate Repair Cost to Vehicle No :SMD8805S

Quantity	Description	List Price SS	Amount SS
		Total	SS 23,345.11
		Add GST @ 7%	1,634.16
		Total Amount Payable	SS 24,979.27
			<u>23892.85</u>

TOTAL: SINGAPORE DOLLAR TWENTY FOUR THOUSAND NINE HUNDRED SEVENTY NINE AND CENTS TWENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

  
 AUTHORIZED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Lij  
 P/P. 09/05/22  
 08 Days.

Supplementary: 54774.  
 Total: 18739.47

18739.47      09 Days.

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST 201300201N

M/S: AUTO & GENERAL INSURANCE (S) PTE LTD  
 190 CLEMENCEAU AVE #03-01  
 SINGAPORE SHOPPING CENTRE  
 SINGAPORE 239924  
 TEL: 6221 2199 FAX: 6725 0853  
 ATTN: Motor Claim Department

Estimate No: **EST2200144**  
 Date: 08 Aug 2022

Veh Reg No: **SMD8805S**  
 Make/Model: AUDI A3 SEDAN 1.4  
 TFSI COD S TRONIC  
 Chasis No: WAUZZZ8V0J1078160  
 Reg. Date: 10/09/2018  
 Your Ref No: SMM1721Z

Claim Type: Third Party  
 Accident Date: 03/05/2022  
 TP Veh Reg No: SMM1721Z

## Estimate Repair Cost to Vehicle No :SMD8805S

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Supplementary Parts to Repair		
	<b>List Price</b>		
1	1 PC REAR PANEL LOWER <i>Distorted</i>	379.00	✓
2	1 PC SPARE TYRE PANEL TOP SPONGE <i>Delud</i>	198.20	✓
3	1 PC REAR SIDE RETAINER BRACKET LH <i>Brnd</i>	31.40	✓
		608.60	
	Less 10%	60.86	547.74
	Total		SS 547.74
	GST Amount		SS 38.34
	Total Amount Payable		SS 586.08

*whatsapp to  
 adrian  
 8/8/22  
 9*

*14.15 per*

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

*Supplementary: 547.74.*