

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TP III  
 Asher.

SHARIL BIN MOHAMAD  
 BLK 647 WOODLANDS RING ROAD #03-68  
 SINGAPORE 730647

## TAX INVOICE

Repair Code : CLM17188

Date in : 07/05/2022

Vehicle Num. : SMH1951C

Model : HONDA FREED 1.5G CVT

Chassis/Eng# : GB51091094/L15B4313054

Contact : 81983846

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehd</i>	1	819.40	✓ 819.40
REAR BUMPER REFLECTOR L/R <i>men</i>	2	42.80	+ 85.60
REAR BUMPER SIDE BRACKET L/R <i>sh</i>	2	42.80	✓ 85.60
REAR BUMPER SIDE RETAINER L/R <i>n</i>	2	24.90	✓ 49.80
REAR BUMPER UNDER COVER <i>torn</i>	1	138.40	✓ 138.40
REAR END PANEL (INNER) <i>Dented</i>	1	96.20	✓ 96.20
REAR END PANEL (OUTER) <i>Dented</i>	1	523.70	✓ 523.70
REAR END PANEL ANTENNA SENSOR <i>could</i>	1	90.40	✓ 90.40
REAR END PANEL BRACKET L/R <i>Bed</i>	2	40.00	✓ 80.00
REAR END PANEL BUZZLE SENSOR <i>Control No in</i>	1	80.20	+ 80.20
REAR END PANEL INNER TOP GARNISH <i>Dehd</i>	1	115.40	✓ 115.40
REAR END PANEL SIDE GARNISH L/R <i>could</i>	2	98.00	✓ 196.00
REAR FENDER INNER TRIM BOARD L/R <i>Dehd</i>	2	368.20	✓ 736.40
REAR FLOOR PANEL <i>Repair</i>	1	1056.20	<del>+</del> 1,056.20
REAR FLOOR PANEL TOP CARPET <i>compred</i>	1	770.90	✓ 770.90
REAR TAILGATE <i>Distorted</i>	1	1100.90	✓ 1,100.90
REAR TAILGATE 'FREED' EMBLEM <i>3Hw</i>	1	54.90	✓ 54.90
REAR TAILGATE 'LOGO' EMBLEM	1	42.50	✓ 42.50

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

SHARIL BIN MOHAMAD  
 BLK 647 WOODLANDS RING ROAD #03-68  
 SINGAPORE 730647

Contact : 81983846

**TAX INVOICE**

Repair Code : CLM17188

Date in : 07/05/2022

Vehicle Num. : SMH1951C

Model : HONDA FREED 1.5G CVT

Chassis/Eng# : GB51091094/L15B4313054

REAR TAILGATE DAMPER L/R	<i>} New</i>	2	135.40	+	270.80
REAR TAILGATE HINGES L/R	<i>} New</i>	2	59.20	+	118.40
REAR TAILGATE INNER PULL HANDLE	<i>del'd</i>	1	29.40	✓	29.40
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	<i>new</i>	2	9.80	+	19.60
REAR TAILGATE INNER TRIM BOARD	<i>del'd</i>	1	388.90	✓	388.90
REAR TAILGATE LOCK STRIKER	<i>Bent</i>	1	36.40	✓	36.40
REAR TAILGATE MECHANISM LOCK	<i>del'd</i>	1	157.20	✓	157.20
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>new</i>	2	39.40	+	78.80
REAR TAILGATE OUTER CHROME HANDLE	<i>del'd</i>	1	320.40	✓	320.40
REAR TAILGATE OUTER LOCK OPENER SWITCH	<i>del'd</i>	1	103.40	✓	103.40
REAR TAILGATE REFLECTOR L/R	<i>del'd</i>	2	330.20	✓	660.40
REAR TAILGATE WEATHER STRIP	<i>del'd</i>	1	168.40	✓	168.40
REAR TAILGATE WINDSCREEN	<i>shattered</i>	1	1052.40	✓	1,052.40
REAR TAILGATE WINDSCREEN MOULDING	<i>new</i>	1	149.80	✓	149.80
REAR TAILGATE WIPER MOTOR	<i>del'd</i>	1	370.90	✓	370.90
REAR TAILGATE WIPER MOTOR ARM	<i>del'd</i>	1	59.40	✓	59.40
REAR TAILGATE WIPER MOTOR ARM BLADE	<i>del'd</i>	1	42.80	✓	42.80
REAR TAILGATE WIPER MOTOR ARM COVER	<i>del'd</i>	1	20.00	✓	20.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

SHARIL BIN MOHAMAD  
 BLK 647 WOODLANDS RING ROAD #03-68  
 SINGAPORE 730647

Contact : 81983846

**TAX INVOICE**

Repair Code : CLM17188

Date in : 07/05/2022

Vehicle Num. : SMH1951C

Model : HONDA FREED 1.5G CVT

Chassis/Eng# : GB51091094/L15B4313054

REAR TAILLAMP L/R	<i>could</i>	9719.10	2	629.40	✓	1,258.80
REAR TAILLAMP TOP SIDE GARNISH L/R	<i>HE M</i>	7775.28	2	105.00	+	210.00
Subtotal before discount						11,638.70
Percentage discount 20%						2,327.74
<b>Sub-total 1</b>						<b>9,310.96</b>
REAR BUMPER CLIPS - SET	<i>Nu</i>		1	80.00	<i>30</i>	<del>80.00</del>
REAR BUMPER REVERSE SENSOR - SET	<i>Dygd</i>		1	280.00	<i>20</i>	<del>280.00</del>
REAR BUMPER STICKER	<i>nu</i>		1	300.00	<i>120</i>	<del>300.00</del>
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>nu</i>		1	40.00	<i>20</i>	<del>40.00</del>
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	<i>nu</i>		2	50.00	<i>60</i>	<del>100.00</del>
REAR FLOOR PANEL INSULATOR MAT	<i>HE nu</i>		1	300.00	<i>7</i>	<del>300.00</del>
REAR TAILGATE CAMERA	<i>could</i>		1	800.00	<i>380</i>	<del>800.00</del>
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	<i>nu</i>		1	50.00	<i>30</i>	<del>50.00</del>
REAR TAILGATE NUMBER PLATE	<i>set</i>		1	25.00	✓	25.00
REAR TAILGATE NUMBER PLATE HOLDER	<i>del</i>		1	50.00	<i>30</i>	<del>50.00</del>
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	<i>nu</i>		1	50.00	<i>10</i>	<del>50.00</del>
REAR TAILGATE VIDEO RECORDER	<i>Dygd</i>		1	900.00	<i>350</i>	<del>900.00</del>
REAR TAILGATE WINDSCREEN SEALANT	<i>nu</i>		1	80.00	<i>60</i>	<del>80.00</del>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

SHARIL BIN MOHAMAD  
 BLK 647 WOODLANDS RING ROAD #03-68  
 SINGAPORE 730647

Contact : 81983846

**TAX INVOICE**

Repair Code : CLM17188

Date in : 07/05/2022

Vehicle Num. : SMH1951C

Model : HONDA FREED 1.5G CVT

Chassis/Eng# : GB51091094/L15B4313054

REAR TAILLAMP CLIPS L/R- SET <i>m</i>	<i>1535</i>	2	25.00	<i>20.</i>	<del>50.00</del>
REAR TAILLAMP TOP SIDE GARNISH CLIPS L/R - SET <i>ncc</i>		2	25.00	<i>+</i>	<del>50.00</del>
Subtotal before discount					3,155.00
Percentage discount 0%					0.00
<b>Sub-total 2</b>					<b>3,155.00</b>
<b>Parts-total</b>					<b>12,465.96</b>

**LABOUR**

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.				<i>✓</i>	80.00
To remove, reinstall tailgate windscreen				<i>120.</i>	<del>150.00</del>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)				<i>80.</i>	<del>120.00</del>
To send vehicle for cleaning, shampoo, upholstery and cushion seat.				<i>80.</i>	<del>200.00</del>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.				<i>800.</i>	<del>1,200.00</del>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.				<i>1,100</i>	<del>2,000.00</del>
To apply anti-rust chemical on repaired and replaced panel.				<i>80.</i>	<del>120.00</del>
To remove, reinstall tailgate mechanism and check for function				<i>✓</i>	80.00
<b>Labour Total</b>					<b>3,950.00</b>
<b>Parts &amp; Labour Total</b>					<b>16,415.96</b>

*Admin Li*  
*L/S 10/05/22*

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

*08000*  
*total: 11750.28*  
*L/S: G.H.K ✓*