



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2206299

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 11/10/2022
Reference CC4/LPC22004313/Upa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 4718X
Insured Veh. XD 2001D
Claim No. 21/22/22/VC05/025769
Policy No. Z21VC05008274
Accident Date 07/05/2022
Inspection Date 10/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22004313/Upa3q2 Date: 11/10/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 2001D	Veh. Inspected	SLN 4718X	
Policy No.	Z21VC05008274	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025769	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	09/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11204318	Colour	BROWN	
Odometer	111852 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2022	Inspection Date	10/05/2022	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4718X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
4	REAR WINDSCREEN MOULDING @\$30.00 (WCP)	NECESSARY	120.00	120.00
1	REAR GATE (WCP)	BADLY DENTED	650.00	650.00
1	REAR GATE OUTER GARNISH (WCP)	CRACKED	145.00	145.00
1	REAR GATE 'VEZEL' PLATE (WCP)	NECESSARY	45.00	45.00
1	REAR GATE LOCK (WCP)	TWISTED / JAMMED	90.00	90.00
1	REAR GATE INNER RUBBER (WCP)	TWISTED	85.00	85.00
1	REAR GATE INNER TRIMBOARD (WCP)	CRACKED	155.00	155.00
15	TRIMBOARD CLIPS @\$2.00 (WCP)	NECESSARY	30.00	30.00
2	REAR GATE LAMP @\$165.00 (WCP)	CRACKED	330.00	330.00
1	REAR BUMPER (CTR) (WCP)	DEFORMED	230.00	230.00
1	REAR BUMPER CORNER (WCP)	N/S DENTED / O/S TO REPAIR SEE LABOUR	210.00	105.00
1	REAR BUMPER RETAINER LH (WCP)	BENT	20.00	20.00
10	REAR BUMPER CLIPS @\$2.00 (WCP)	NECESSARY	20.00	20.00
2	TAIL LAMP @\$285.00 (WCP)	CRACKED	570.00	570.00
1	REAR END PANEL (WCP)	TO REPAIR SEE LABOUR	350.00	-
1	REAR END PANEL TOP TRIM (WCP)	NOT NECESSARY	55.00	-
	COST PLUS 20%		621.00	519.00
			3,726.00	3,114.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GUM (SN)	NECESSARY	60.00	40.00
1	REAR GATE SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR NUMBER PLATE (SN)	CRACKED	40.00	40.00
			220.00	120.00
<u>LABOUR</u>				
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX REAR WINDSCREEN.		120.00	120.00

Report Ref No. CC4/LPC22004313/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX REAR BOOT UPHOLSTERY .		100.00	60.00
	TRANSFER REAR GATE COMPONENTS.		100.00	60.00
	CAVITY PROTECTION .		100.00	40.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF REAR BUMPER CORNER O/S AND REAR END PANEL .		800.00	580.00
	SPRAY PAINTING.		800.00	700.00
			2,050.00	1,580.00
GRAND TOTAL			5,996.00	4,814.00
RECOMMENDED COST OF REPAIRS				4,814.00

Report Ref No. CC4/LPC22004313/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4718X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4718X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4718X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 4718X

RE-INSPECTION

